

- FORGE POND DAM & DIKE-
PHASE I
INSPECTION / EVALUATION REPORT



Dam Name: Forge Dam & Dike
State Dam ID#: 2-8-111-2 Dam & 2-8-111-3 Dike
NID#: MA00488 Dam & MA00489 Dike
Owner: Town of Granby
Owner Type: Municipal
Town: Granby
Consultant: Lenart Consulting Service, LLC
Date of Inspection: March 23, 2020

Executive Summary

This Phase I Inspection/Evaluation Report details the inspection and evaluation of Forge Pond Dam and Forge Pond Dike, located in Granby, Massachusetts. The inspection was conducted on March 23, 2020 by Lenart Consulting Service, LLC. Forge Pond Dam and Forge Pond Dike are classified as an **Intermediate** sized, **Significant (Class II)** hazard potential dam structures.

The overall physical condition of Forge Pond Dam and Forge Pond Dike, collectively, were found to be **Poor** based on the Office of Dam Safety's September 2008 rating guidelines. The following deficiencies were noted during the inspection and evaluation:

Dam Location:

1. There is spalling, transverse structural cracks and missing pieces of concrete in the upstream training walls at both abutments.
2. The rubber tire retaining wall immediately downstream of the right end of the spillway is failing, jeopardizing the residence adjacent to the discharge channel and the right abutment.
3. Erosion of embankment soils has occurred behind the left spillway training wall at its downstream end. This condition has remained the same since the last inspection.
4. The hydraulic adequacy of the spillway to accommodate the SDF flows should be evaluated.
5. Maintenance is required including stump removal and control of woody vegetation

6. Dike Location:

1. The gate is not operable and materials of construction require replacement.
2. The stop-logs are deteriorated and materials of construction require replacement.
3. Stone masonry walls require repair.

It is recommended that the following actions be taken to address the deficiencies found at the dam and dike during this inspection and evaluation:

General:

- Perform an updated, detailed Hydraulic & Hydrologic analysis to determine the design storm discharge and hydraulic adequacy of spillway.
- Prepare a formal Operations & Maintenance Manual for the dam and the dike.

Dam & Dike Location:

- Remove tree stumps and root systems.
- Repair left concrete wall at the dam.

- Fill the depressed area behind the spillway training wall at the right abutment.
- Establish grass surface on dam crest where soils are exposed.
- Repair downstream stone masonry walls at dike.
- Remove Repair/replace the concrete wall on the right side of the spillway.
- Replace the tire retaining wall with a proper structure to provide stability.
- Repair eroded area behind the left spillway training wall.
- Extend left downstream concrete training wall or augment with rip rap.
- Repair gate and operator at dike.
- Replace the stop logs at dike

Some of the recommendations should be performed under the direction of a registered professional engineer familiar with the methods and materials used in the design, construction and repair of dams.

Dam Evaluation Summary Detail Sheet

1. NID ID: MA00488		4. Inspection Date: March 23, 2020	
2. Dam Name: Forge Pond Dam		5. Last Insp. Date: July 10, 2014	
3. Dam Location: Granby, MA		6. Next Inspection: March 23, 2025	
7. Inspector: Cathleen A. Benben			
8. Consultant: Lenart Consulting Services, LLC			
9. Hazard Code: Significant		9a. Is Hazard Code Change Requested?: No	
10. Insp. Frequency: 5 Years		11. Overall Physical Condition of Dam: POOR	
12. Spillway Capacity (% SDF) 0-50% of the SDF or Unknown			
E1. Design Methodology: 3		E7. Low-Level Discharge Capacity: 1	
E2. Level of Maintenance: 2		E8. Low-Level Outlet Physical Condition: 2	
E3. Emergency Action Plan: 5		E9. Spillway Design Flood Capacity: 1	
E4. Embankment Seepage: 4		E10. Overall Physical Condition of the Dam: 2	
E5. Embankment Condition: 4		E11. Estimated Repair Cost: \$375,000	
E6. Concrete Condition: 3			

Evaluation Description

E1: DESIGN METHODOLOGY

1. Unknown Design – no design records available
2. No design or post-design analyses
3. No analyses, but dam features appear suitable
4. Design or post design analysis show dam meets most criteria
5. State of the art design – design records available & dam meets all criteria

E2: LEVEL OF MAINTENANCE

1. Dam in disrepair, no evidence of maintenance, no O&M manual
2. Dam in poor level of upkeep, very little maintenance, no O&M manual
3. Dam in fair level of upkeep, some maintenance and standard procedures
4. Adequate level of maintenance and standard procedures
5. Dam well maintained, detailed maintenance plan that is executed

E3: EMERGENCY ACTION PLAN

1. No plan or idea of what to do in the event of an emergency
2. Some idea but no written plan
3. No formal plan but well thought out
4. Available written plan that needs updating
5. Detailed, updated written plan available and filed with MADCR, annual training

E4: SEEPAGE (Embankments, Foundations, & Abutments)

1. Severe piping and/or seepage with no monitoring
2. Evidence of monitored piping and seepage
3. No piping but uncontrolled seepage
4. Minor seepage or high volumes of seepage with filtered collection
5. No seepage or minor seepage with filtered collection

E5: EMBANKMENT CONDITION (See Note 1)

1. Severe erosion and/or large trees
2. Significant erosion or significant woody vegetation
3. Brush and exposed embankment soils, or moderate erosion
4. Unmaintained grass, rodent activity and maintainable erosion
5. Well maintained healthy uniform grass cover

E6: CONCRETE CONDITION (See Note 2)

1. Major cracks, misalignment, discontinuities causing leaks, seepage or stability concerns
2. Cracks with misalignment inclusive of transverse cracks with no misalignment but with potential for significant structural degradation
3. Significant longitudinal cracking and minor transverse cracking
4. Spalling and minor surface cracking
5. No apparent deficiencies

E7: LOW-LEVEL OUTLET DISCHARGE CAPACITY

1. No low level outlet, no provisions (e.g. pumps, siphons) for emptying pond
2. No operable outlet, plans for emptying pond, but no equipment
3. Outlet with insufficient drawdown capacity, pumping equipment available
4. Operable gate with sufficient drawdown capacity
5. Operable gate with capacity greater than necessary

E8: LOW-LEVEL OUTLET PHYSICAL CONDITION

1. Outlet inoperative needs replacement, non-existent or inaccessible
2. Outlet inoperative needs repair
3. Outlet operable but needs repair
4. Outlet operable but needs maintenance
5. Outlet and operator operable and well maintained

E9: SPILLWAY DESIGN FLOOD CAPACITY

1. 0 - 50% of the SDF or unknown
2. 50-90% of the SDF
3. 90 - 100% of the SDF
4. >100% of the SDF with actions required by caretaker (e.g. open outlet)
5. >100% of the SDF with no actions required by caretaker

E10: OVERALL PHYSICAL CONDITION OF DAM

1. UNSAFE – Major structural, operational, and maintenance deficiencies exist under normal operating conditions
2. POOR - Significant structural, operation and maintenance deficiencies are clearly recognized under normal loading conditions
3. FAIR - Significant operational and maintenance deficiencies, no structural deficiencies. Potential deficiencies exist under unusual loading conditions that may realistically occur. Can be used when uncertainties exist as to critical parameters
4. SATISFACTORY - Minor operational and maintenance deficiencies. Infrequent hydrologic events would probably result in deficiencies.
5. GOOD - No existing or potential deficiencies recognized. Safe performance is expected under all loading including SDF

E11: ESTIMATED REPAIR COST

Estimation of the total cost to address all identified structural, operational, maintenance deficiencies. Cost shall be developed utilizing standard estimating guides and procedures

Changes/Deviations to Database Information since Last Inspection

Dam Evaluation Summary Detail Sheet

1. NID ID: MA00489		4. Inspection Date: March 23, 2020	
2. Dam Name: Forge Pond Dike		5. Last Insp. Date: July 10, 2020	
3. Dam Location: Granby, MA		6. Next Inspection: March 23, 2025	
7. Inspector: Cathleen A. Benben			
8. Consultant: Lenart Consulting Services, LLC			
9. Hazard Code: Significant		9a. Is Hazard Code Change Requested?: No	
10. Insp. Frequency: 5 Years		11. Overall Physical Condition of Dam: POOR	
12. Spillway Capacity (% SDF) No spillway at dike			
E1. Design Methodology: 3		E7. Low-Level Discharge Capacity: 2	
E2. Level of Maintenance: 2		E8. Low-Level Outlet Physical Condition: 2	
E3. Emergency Action Plan: 5		E9. Spillway Design Flood Capacity: 1	
E4. Embankment Seepage: 4		E10. Overall Physical Condition of the Dam: 2	
E5. Embankment Condition: 2		E11. Estimated Repair Cost: \$50,000	
E6. Concrete Condition: 2			

Evaluation Description

E1: DESIGN METHODOLOGY

1. Unknown Design – no design records available
2. No design or post-design analyses
3. No analyses, but dam features appear suitable
4. Design or post design analysis show dam meets most criteria
5. State of the art design – design records available & dam meets all criteria

E2: LEVEL OF MAINTENANCE

1. Dam in disrepair, no evidence of maintenance, no O&M manual
2. Dam in poor level of upkeep, very little maintenance, no O&M manual
3. Dam in fair level of upkeep, some maintenance and standard procedures
4. Adequate level of maintenance and standard procedures
5. Dam well maintained, detailed maintenance plan that is executed

E3: EMERGENCY ACTION PLAN

1. No plan or idea of what to do in the event of an emergency
2. Some idea but no written plan
3. No formal plan but well thought out
4. Available written plan that needs updating
5. Detailed, updated written plan available and filed with MADCR, annual training

E4: SEEPAGE (Embankments, Foundations, & Abutments)

1. Severe piping and/or seepage with no monitoring
2. Evidence of monitored piping and seepage
3. No piping but uncontrolled seepage
4. Minor seepage or high volumes of seepage with filtered collection
5. No seepage or minor seepage with filtered collection

E5: EMBANKMENT CONDITION (See Note 1)

1. Severe erosion and/or large trees
2. Significant erosion or significant woody vegetation
3. Brush and exposed embankment soils, or moderate erosion
4. Unmaintained grass, rodent activity and maintainable erosion
5. Well maintained healthy uniform grass cover

E6: CONCRETE CONDITION (See Note 2)

1. Major cracks, misalignment, discontinuities causing leaks, seepage or stability concerns
2. Cracks with misalignment inclusive of transverse cracks with no misalignment but with potential for significant structural degradation
3. Significant longitudinal cracking and minor transverse cracking
4. Spalling and minor surface cracking
5. No apparent deficiencies

E7: LOW-LEVEL OUTLET DISCHARGE CAPACITY

1. No low level outlet, no provisions (e.g. pumps, siphons) for emptying pond
2. No operable outlet, plans for emptying pond, but no equipment
3. Outlet with insufficient drawdown capacity, pumping equipment available
4. Operable gate with sufficient drawdown capacity
5. Operable gate with capacity greater than necessary

E8: LOW-LEVEL OUTLET PHYSICAL CONDITION

1. Outlet inoperative needs replacement, non-existent or inaccessible
2. Outlet inoperative needs repair
3. Outlet operable but needs repair
4. Outlet operable but needs maintenance
5. Outlet and operator operable and well maintained

E9: SPILLWAY DESIGN FLOOD CAPACITY

1. 0 - 50% of the SDF or unknown
2. 50-90% of the SDF
3. 90 - 100% of the SDF
4. >100% of the SDF with actions required by caretaker (e.g. open outlet)
5. >100% of the SDF with no actions required by caretaker

E10: OVERALL PHYSICAL CONDITION OF DAM

1. UNSAFE – Major structural, operational, and maintenance deficiencies exist under normal operating conditions
2. POOR - Significant structural, operation and maintenance deficiencies are clearly recognized under normal loading conditions
3. FAIR - Significant operational and maintenance deficiencies, no structural deficiencies. Potential deficiencies exist under unusual loading conditions that may realistically occur. Can be used when uncertainties exist as to critical parameters
4. SATISFACTORY - Minor operational and maintenance deficiencies. Infrequent hydrologic events would probably result in deficiencies.
5. GOOD - No existing or potential deficiencies recognized. Safe performance is expected under all loading including SDF

E11: ESTIMATED REPAIR COST

Estimation of the total cost to address all identified structural, operational, maintenance deficiencies. Cost shall be developed utilizing standard estimating guides and procedures

Changes/Deviations to Database Information since Last Inspection


Preface

The following three paragraphs were excerpted from the sample dam inspection format provided by the Massachusetts Department of Conservation and Recreation. The paragraphs are valid for the dam inspection and assessment provided in this report.

The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigations and analyses involving topographic mapping, subsurface investigations, testing and detailed computational evaluations are beyond the scope of this report.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection, along with data available to the inspection team. In cases where an impoundment is lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions, which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is critical to note that the condition of the dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions would be detected.



David M. Lenart, P.E.
Massachusetts License No.:27995
Lenart Consulting Service



Executive Summary**Dam Evaluation Summary Detail Sheet****Preface****Section 1 Description of Project**

1.1	General.....	1-1
1.1.1	Authority.....	1-1
1.1.2	Purpose of Work.....	1-1
1.1.3	Definitions.....	1-1
1.1.4	Figures	1-1
1.2	Description of Project.....	1-1
1.2.1	Location.....	1-1
1.2.2	Owner/Operator.....	1-2
1.2.3	Purpose of the Dam.....	1-2
1.2.4	Description of the Dam and Appurtenances	1-2
1.2.5	Operations and Maintenance.....	1-3
1.2.6	DCR Size Classification.....	1-3
1.2.7	DCR Hazard Potential Classification	1-3
1.3	Engineering Data	1-4
1.3.1	Drainage Area.....	1-4
1.3.2	Reservoir	1-4
1.3.3	Discharges at the Dam Site	1-5
1.3.4	General Elevations (feet).....	1-5
1.3.5	Main Spillway.....	1-5
1.3.6	Additional Information	1-6
1.3.7	Design and Construction Records	1-6
1.3.8	Operating Records.....	1-6
1.4	Summary Data Table.....	1-6

Section 2 Inspection

2.1	Visual Inspection.....	2-1
2.1.1	General Findings	2-1
2.1.2	Dam.....	2-1
2.1.3	Dike.....	2-2
2.1.4	Appurtenant Structures.....	2-4
2.1.5	Downstream Area.....	2-5
2.1.6	Reservoir Area	2-5
2.2	Caretaker Interview.....	2-5
2.3	Operation and Maintenance Procedures.....	2-6
2.3.1	Operational Procedures	2-6

2.3.2 Maintenance of Dam and Dike.....2-6
2.3.3 Emergency Warning System2-6
2.4 Hydrologic/Hydraulic Data2-6
2.5 Structural Stability/Overtopping Potential2-6
2.5.1 Embankment Structural Stability.....2-6
2.5.2 Structural Stability of Non-Embankment Structures.....2-7
2.5.3 Seepage Stability2-7
2.5.4 Overtopping Potential2-7

Section 3 Assessments and Recommendations

3.1 Assessments.....3-1
3.2 Studies and Analyses.....3-2
3.3 Yearly Recommendations3-2
3.4 Recommendations, Maintenance, and Minor Repairs3-2
3.5 Remedial Measures.....3-3
3.6 Alternatives3-3
3.7 Opinion of Probable Costs.....3-3

Tables

- 1.1 Summary Data Table

Figures

- Figure 1: Site Locus
- Figure 2: Aerial Photograph
- Figure 3: Drainage Area
- Figure 4: Downstream Area

Appendices

- A Photographs
- B Inspection Checklist
- C Previous Reports and References
- D Definitions

Section 1

Description of Project

1.1 General

1.1.1 Authority

The Town of Granby has retained Lenart Consulting Service, LLC to perform a visual inspection and develop a report of conditions for the Forge Pond Dam and Forge Pond Dike in Granby, Massachusetts. This inspection and report were performed in accordance with MGL Chapter 253, Sections 44-50 of the Massachusetts General Laws as amended by Chapter 330 of the Acts of 2002.

1.1.2 Purpose of Work

The purpose of this investigation is to inspect and evaluate the present condition of the dam and appurtenant structures in accordance with 302 CMR 10.07 to provide information that will assist in both prioritizing dam repair needs and planning/conducting maintenance and operation.

The investigation is divided into four parts: 1) obtain and review available reports, investigations, and data previously submitted to the owner pertaining to the dam and appurtenant structures; 2) perform a visual inspection of the site; 3) evaluate the status of an emergency action plan for the site and; 4) prepare and submit a final report presenting the evaluation of the structure, including recommendations and remedial actions, and opinion of probable costs.

1.1.3 Definitions

To provide the reader with a better understanding of the report, definitions of commonly used terms associated with dams are provided in Appendix D. Many of these terms may be included in this report. The terms are presented under common categories associated with dams which include: 1) orientation; 2) dam components; 3) size classification; 4) hazard classification; and 5) miscellaneous.

1.1.4 Figures

Figures were created for this report to aid the reader in understanding the dam, its features, and the surrounding area. Figure 1 presents a topographic image showing the dam and dike location and surrounding area. Figure 2 presents an aerial overview of the dam and dike and surrounding area. Figure 3 presents a topographic image showing the watershed area associated with the dam. Site sketches of the dam and dike, which serve as photo location plans showing location and orientation of photos taken during the inspection, are also included in Appendix A.

1.2 Description of Project

1.2.1 Location

Forge Pond Dam and Forge Pond Dike are located on Forge Pond in the Town of Granby, Massachusetts in Hampshire County. The dam location is shown on the USGS quadrangle map at coordinates 42.274511, -72.470850. The dike is located at

coordinates 42.273763, -72.470885. Access to both structures is from School Street. See Figure 1 and 2, the USGS site locus map and an aerial photograph site locus appended to this report in the Figures section.

1.2.2 Owner/Operator

	Dam and Dike Owner	Dam and Dike Caretaker
Name	Town of Granby thru its Board of Selectmen	Town of Granby thru its Board of Selectmen
Mailing Address	Senior Center Building 2nd Floor 10-B West State Street	Senior Center Building 2nd Floor 10-B West State Street
Town	Granby, MA	Granby, MA
Daytime Phone	(413) 467-7177	(413) 467-7177
Emergency Phone	911	911
Email Address	Not Available	Not Available

Current owner and caretaker data is also included in Table 1.1.

1.2.3 Purpose of the Dam

Forge Pond Dam was constructed to enlarge the impoundment of Forge Pond. The pond was originally utilized for a forge operation during the Civil War but now is utilized for recreational and conservation purposes. The dike section was constructed to provide an outlet for the forge operation but now is a drain for lowering and controlling the pond level.

1.2.4 Description of the Dam and Appurtenances

The dam at Forge Pond consists of two (2) structures, the main dam where the spillway is located, and the dike, where the low-level outlet is located.

The dam is approximately 115 feet long and 13.5 feet high. The dam is an earthen embankment with a spillway that is a combination of dry-stone masonry and concrete construction. The embankment section of the dam is about 33 feet long with a crest width of 12 feet. The upstream face is a vertical concrete wall and the downstream slope is very flat. A sketch from an inspection report from 1975 indicated that the embankment was constructed with a stone masonry wall along its downstream face. If the wall still exists, it has been backfilled and is no longer visible. The downstream slope and crest are grass covered.

The spillway is an 82-foot long broad-crested weir located at the right abutment. Outflow from the pond passes over the spillway crest, dropping approximately 11.0 feet

to the brook bed discharge channel at the base of the dam. The dry-stone masonry section of the spillway is capped with concrete, beginning at the right abutment and is 24-feet in length. The remaining portion of the spillway structure is concrete and is offset from and parallel to the stone masonry section of the spillway. The concrete and stone portions of the spillway are connected by a concrete wall section which is perpendicular to both walls and is about 3-feet long. The downstream face of the main concrete spillway is battered. Ledge outcropping is located at the left end of the spillway.

The upstream apron of the spillway is rip rapped to the stone masonry section, and concrete paved to the concrete section. The apron has an approximate slope of 6:1 extending to the gravel bottom of the pond. There are concrete training walls on each side of the spillway. No provision for flashboards exists at the spillway.

The dike is an "L" shaped earth fill embankment located approximately 200-feet south of the main dam, with a reinforced concrete retaining wall and mortared stone fascia on the upstream face. The dike is about 90 feet long, 10.7 feet high, and 19 feet wide at the crest. The lowest 2.5 feet of the vertical face is actually exposed bedrock. The downstream slope on the right side is 2H:1V and is grass covered, as is the crest. The downstream slope to the left of the outlet control structure is stepped with a stone masonry retaining wall approximately 2.5 feet high beginning at the top of the embankment.

Near the bend in the "L", is a control structure with a 36-inch diameter outlet that functions as a drain for the pond. The control structure is constructed of reinforced concrete with a footing that sits on bedrock. The structure is 6 feet by 8 feet and the top of the structure extends 20-inches above the top of the embankment. There is a rack and pinion operated sluice gate on the upstream face of the structure and stop logs within the structure for controlling flow. The invert elevation of the 36-inch diameter outlet is 266.0. The outlet line terminates at the dry stone masonry headwall on the downstream face of the dike. The discharge channel is stone-lined and has a restricted cross-section before it crosses beneath School Street by means of a 36-inch diameter corrugated metal pipe culvert.

1.2.5 Operations and Maintenance

Forge Pond Dam and Dike are operated and maintained by the Town of Granby, with the assistance of the Granby Highway Department. Currently there are no formal operating procedures for these structures. The site is not checked on a regular basis, nor is regular maintenance carried out.

1.2.6 DCR Size Classification

Forge Pond Dam has a maximum structural height of 13.5 feet and Forge Pond Dike has a maximum structural height of 10.7 feet. The maximum storage capacities for the dam and the dike are 600 and 540 acre-feet, respectively. In accordance with Department of Conservation and Recreation classification, under Commonwealth of Massachusetts Regulations 302 CMR Dam Safety revised November 4, 2005, both the dam and dike at Forge Pond are **Intermediate** size structures.

1.2.7 DCR Hazard Potential Classification

Forge Pond Dam is located 300 feet upstream of School Street and a residence is situated at the downstream side of the right abutment. It is estimated that failure of

Forge Pond Dam at maximum pool could impact the house with possible loss of life, and possibly overtop School Street. Therefore, in accordance with Department of Conservation and Recreation Dam Safety classification procedures, under the Commonwealth of Massachusetts Regulations 302 CMR 10.00 as revised November 4, 2005, Forge Pond Dam is classified as a **Significant** (Class II) hazard potential dam. The outflow from Forge Pond Dike would not impact the residence adjacent to the dam, however, flow past School Street is restricted by an undersized culvert. Therefore, Forge Pond Dike is also classified as a **Significant** (Class II) hazard due to the potential impacts to School Street.

1.3 Engineering Data

The following sections are based on field measurements, review of USGS and MassGIS mapping and available design and construction information from previously submitted reports listed in Appendix C. The information presented in this section is intended to provide an overview of the dam and impoundment.

The water surface elevation of 271.0 at Forge Pond, as shown on the USGS Belchertown Quadrangle, Massachusetts, was adopted as the spillway crest elevation. All other elevations given in this report were estimated from the assumed spillway crest elevation. Elevations refer to National Geodetic Vertical Datum (NGVD).

1.3.1 Drainage Area

The total drainage area contributing to Forge Pond is approximately 14.2 square miles. The pond is surrounded by hilly terrain and development within the watershed is light with undeveloped areas being heavily wooded. The drainage area includes outflow from Metacomet Lake. About 5.6 percent of the drainage area is made up of ponds and swamps. Figure 3, included in the Figures section of the report, outlines the drainage area boundary for Forge Pond.

1.3.2 Reservoir

	Impoundment Elevation (feet)	Surface Area (acres)	Storage Volume (acre-feet)
Normal Pool	271.0	72	380 (dam) 320 (dike)
Maximum Pool	273.5	85	600 (dam) 540 (dike)
SDF Pool (100-yr storm)	Unknown	Unknown	Unknown
Max Pool ½ PMF (from 1981 H&H analysis)	276.0	113	820 (dam)* 760 (dike)*

* Estimated storage volume adjusted based on field observed elevations.

1.3.3 Discharges at the Dam Site

The normal discharge past Forge Pond Dam is over the stone masonry and concrete spillway at elevation 271.0 with a weir length of 82 feet. Downstream of the spillway, the discharge channel averages 35 feet in width and flows through three (3) 8 x 6-foot corrugated metal pipe arch culverts under School Street.

The outlet for the pond is a 36-inch diameter reinforced concrete pipe with a sluice gate and stop log control structure located at Forge Pond Dike. The outlet pipe discharges to a small stone-lined channel which passes under School Street through a 36-inch diameter corrugated metal pipe.

The discharges past the dam for various pool elevations are summarized below:

Discharges are in cubic feet per second (cfs):

A. Maximum Known Flood at the Dam Site	Unknown
B. Spillway Capacity With Water Level at the Top of the Dam	1,005
C. Design Flood Outflow (100-year flood)	Unknown
D. Low Level Outlet Capacity With Water Level at the Top of the Dam	86

1.3.4 General Elevations (feet)

Elevations presented below are based on an assumed spillway crest elevation and field measurements presented in the previous inspection report.

A. Top Of Dam	273.5
B. Top of Dike	273.5
C. Spillway Design Flood Pool	Unknown
D. Normal Pool	271.0
E. Spillway Crest	271.0
F. Upstream Water At Time Of The Inspection	271.1
G. Streambed At Toe Of The Dam	260.0
H. Low Point Along Toe Of The Dam	260.0

1.3.5 Main Spillway

A. Type	Concrete and stone masonry weir
B. Length	82.0
C. Crest Elevation	271.0
D. Upstream Channel	Forge Pond
E. Downstream Channel	Bachelor Brook
F. Channel Bottom Elevation	260.0
G. Downstream Water Elevation	261.0±

1.3.6 Additional Information

Control Structure at Forge Pond Dike

A.	Top of Concrete structure (grating cover)	275.3
B.	Bottom of Concrete Structure	266.0
C.	Top of Stop Logs Inside Structure	271.0
E.	Downstream Channel	262.8

1.3.7 Design and Construction Records

Design and construction records are not available. The dam was originally constructed around 1800. The original main dam structure included a wooden plank apron and spillway crest at the stone masonry section at the right side. In 1977, the present dike, an earthfill dam with a concrete retaining wall and stone fascia, was designed by MGS, Michael G. Suprenant, Consulting Engineer, to replace an existing concrete dam. Improvement plans for the dike and outlet structure are on file at the office of the Granby Conservation Commission. Reconstruction of the dike and outlet structure was completed in 1978. It is also assumed that in 1978 the wooden plank apron was replaced with riprap and a concrete cap was added to the stone masonry section of the main dam.

1.3.8 Operating Records

There are no operating records available for review. There is no formal operating procedure for this dam or the dike. The structures are not checked on a regularly, and no records of operation are kept.

1.4 Summary Data Table

Table 1.1 and 1.2, summarizing the required Phase I Report data collected as part of this inspection, are presented on the following pages.

1.1 Summary Data Table

Required Phase I Report Data	Data Provided by the Inspecting Engineer	
National ID #	MA00488	
Dam Name	Forge Pond Dam	
Dam Name (Alternate)	Forge Pond Main Dam	
River Name	Bachelor Brook	
Impoundment Name	Forge Pond	
Hazard Class	Significant	
Size Class	Intermediate	
Dam Type	Earthen Embankment w/ concrete/masonry spillway	
Dam Purpose	Recreation	
Structural Height of Dam (feet)	13.5	
Hydraulic Height of Dam (feet)	11	
Drainage Area (sq. mi.)	14.2	
Reservoir Surface Area (acres)	70	Input
Normal Impoundment Volume (acre-feet)	380	
Max Impoundment Volume ((top of dam) acre-feet)	600	
SDF Impoundment Volume* (acre-feet)	Unknown - No H&H	Input
Spillway Type	Broad-crested weir, concrete and stone masonry	
Spillway Length (feet)	82	
Freeboard at Normal Pool (feet)	2.5	
Principal Spillway Capacity* (cfs)	1005	
Auxiliary Spillway Capacity* (cfs)	N/A	
Low-Level Outlet Capacity* (cfs)	see dike	
Spillway Design Flood* (flow rate - cfs)	100-year/no H&H	
Winter Drawdown (feet below normal pool)	N/A	Input
Drawdown Impoundment Vol. (acre-feet)	N/A	Input
Latitude	42.274511	
Longitude	-72.47085	
City/Town	Granby	
County Name	Hampshire	
Public Road on Crest	No	Input
Public Bridge over Spillway	No	Input
EAP Date (if applicable)	No EAP	
Owner Name	Town of Granby	
Owner Address	10B West State Street	
Owner Town	Granby, MA 01033	
Owner Phone	(413) 467-7177	
Owner Emergency Phone	911	
Owner Type	Municipality or Political subdivision	
Caretaker Name	Board of Selectmen	
Caretaker Address	10B West State Street	
Caretaker Town	Granby, MA 01033	
Caretaker Phone	(413) 467-7177	
Caretaker Emergency Phone	911	
Date of Field Inspection	3/23/2020	
Consultant Firm Name	Lenart Consulting Services, LLC	
Inspecting Engineer	Cathleen A. Benben	
Engineer Phone Number	(413) 535-5754	Input

*In the event a hydraulic and hydrologic analysis has not been completed for the dam, indicate "No H&H" in this table, recommendation section shall include specific recommendation to hire a qualified dam engineering consultant to conduct analysis to determine spillway adequacy in conformance with 302 CMR 10.00.

1.1 Summary Data Table

Required Phase I Report Data	Data Provided by the Inspecting Engineer	
National ID #	MA00489	
Dam Name	Forge Pond Dike	
Dam Name (Alternate)	Forge Pond Small Dam	
River Name	Bachelor Brook	
Impoundment Name	Forge Pond	
Hazard Class	Significant	
Size Class	Intermediate	
Dam Type	Earthen Embankment/stone masonry upstream face	
Dam Purpose	Recreation	
Structural Height of Dam (feet)	10.7	
Hydraulic Height of Dam (feet)	8.2	
Drainage Area (sq. mi.)	14.2	
Reservoir Surface Area (acres)	70	Input
Normal Impoundment Volume (acre-feet)	320	
Max Impoundment Volume ((top of dam) acre-feet)	540	
SDF Impoundment Volume* (acre-feet)	Unknown - no H&H	Input
Spillway Type	located at dam	
Spillway Length (feet)	see dam	
Freeboard at Normal Pool (feet)	2.5	
Principal Spillway Capacity* (cfs)	see dam data	
Auxiliary Spillway Capacity* (cfs)	N/A	
Low-Level Outlet Capacity* (cfs)	86	
Spillway Design Flood* (flow rate - cfs)	100-yr/unknown	
Winter Drawdown (feet below normal pool)	N/A	Input
Drawdown Impoundment Vol. (acre-feet)	N/A	Input
Latitude	42.273763	
Longitude	-72.470885	
City/Town	Granby	
County Name	Hampshire	
Public Road on Crest	No	Input
Public Bridge over Spillway	No	Input
EAP Date (if applicable)	2019	
Owner Name	Town of Granby	
Owner Address	10B West State Street	
Owner Town	Granby, MA 01033	
Owner Phone	(413) 467-7177	
Owner Emergency Phone	911	
Owner Type	Municipality or Political subdivision	
Caretaker Name	Board of Selectmen	
Caretaker Address	10B West State Street	
Caretaker Town	Granby, MA 01033	
Caretaker Phone	(413) 467-7177	
Caretaker Emergency Phone	911	
Date of Field Inspection	3/23/2020	
Consultant Firm Name	Lenart Consulting Services, LLC	
Inspecting Engineer	Cathleen A. Benben	
Engineer Phone Number	(413) 535-5754	Input

*In the event a hydraulic and hydrologic analysis has not been completed for the dam, indicate "No H&H" in this table, recommendation section shall include specific recommendation to hire a qualified dam engineering consultant to conduct analysis to determine spillway adequacy in conformance with 302 CMR 10.00.

Section 2 Inspection

2.1 Visual Inspection

Forge Pond Dam and Forge Pond Dike were inspected on March 23, 2020 by Lenart Consulting Service. Following is a summary of the findings from that inspection. At the time of the inspection, the weather was mostly cloudy with a temperature in the mid 40's° F. Photographs to document the current condition of the dam were taken during the inspection and are included in Appendix A. The level of the impoundment at the time of the inspection was 0.2 feet over the spillway crest. No inspection of underwater areas was made. Copies of the inspection checklists are included in Appendix B.

2.1.1 General Findings

In general, Forge Pond Dam and Forge Pond Dike collectively were found to be in **Poor** condition. All trees and vegetation have been cleared from the dam and dike since the 2014 inspection. Stumps have not been removed. The specific concerns are identified in more detail in the sections below.

2.1.2 Dam

- Abutments
 - The right abutment of the main dam consists of a low concrete gravity wall on the upstream side, a portion of which was rebuilt in 1978. The settled area approximately 3 feet square and 1 foot deep noted in the 2014 inspection, located behind the right training wall of the spillway appears unchanged. This settled area was also noted during the 2009 and 1981 inspections.
 - There are horizontal and vertical cracks at several locations along the concrete wall on the upstream side at the right abutment. The condition of the wall has not changed significantly since the last inspection. The exposed footing underneath this wall is not cracked.
 - On the downstream side at the right abutment of the dam there is a fill area forming the side slope of the downstream channel. The slope is reinforced with rubber tires stacked on top of each other. The 2014 inspection report made note of a sketch of the dam showing an 8-foot long, 2 foot wide stone retaining wall at the downstream face of the right abutment. However, a concrete wall section was not observed. The tires appear to be placed on a stone foundation. Failure of this slope will impact the right abutment and jeopardize the house located at the right abutment.
 - The stumps from the large trees that were growing at the top of the slope remain and are near the downstream end of the right concrete training wall.
 - Trees and woody vegetation has been cleared, but stumps and root systems of trees and woody vegetation growing near both abutments and the training walls remain.

- Contact at the left abutment appears good. Outcroppings of bedrock are visible upstream at the abutment.
- Upstream slope
 - There is a concrete wall at the upstream face of the embankment to the left of the spillway. This wall appears to be in fair condition with horizontal and vertical cracks and spalled areas on the vertical face.
 - The small trees and other woody vegetation growing behind and in front of the wall has been cleared, but root systems remain.
- Crest
 - There is a large area adjacent to the spillway on the upstream left side with minor erosion from foot traffic and sparse grass cover.
 - The crest adjacent to the right side of the spillway is private property with various surface conditions, as a result of the homeowner's activity.
- Downstream Slope
 - The downstream slope is grass covered and slopes gradually towards School Street. The grass was cut short before winter and there are some bare areas where woody vegetation has been removed.
 - Erosion of the gravelly soils has occurred behind the left spillway training wall at its downstream end. The undermining of the backfill material at this location was noted in the previous report where there are large gaps between the end of the wall and the boulders placed at the end of the wall has not changed significantly.
- Drains
 - No drains were observed at the dam.
- Instrumentation
 - No instrumentation exists at Dam.
- Access Roads and Gates
 - The dam has unrestricted foot access from School Street.
 - There is a chain link fence along School Street preventing vehicular access when the gates are closed.

2.1.3 Dike

- Abutments
 - Trees and brush previously present at the left and right abutments has been cleared.

- No seepage or unusual movement was observed at the dike abutments.
- Upstream Face
 - The stone masonry along the upstream face is in good condition.
- Crest
 - The crest is grass covered along the section to the right of the outlet control structure, with good overall horizontal and vertical alignment. The grass is not maintained.
 - There is a worn foot path where soils are exposed, approximately 25 feet long, on the crest to the right of the low-level outlet.
 - The small trees and woody vegetation growing on the crest of the dike to the left of the outlet structure and along the top of the stone masonry wall on the downstream edge have been cleared, with stumps and root systems remaining.
- Downstream Slope
 - The downstream slope to the right of the outlet control structure appears stable with no signs of sliding. The slope is approximately 2H:1V and is grass covered. Bedrock is exposed on the slope.
 - Below the short retaining walls at the top of the downstream slope to the left of the low-level structure, the slope has several stumps from trees and brush that were cleared. There is a collapsed section in the wall approximately 2 feet wide.
 - Downstream of the outlet control structure there is a dry-stone masonry wall with the discharge of the 36-inch RCP low level outlet centered in the wall. A small amount of water is leaking past the gate and stop logs in the structure and discharging through the pipe.
 - There are large tree stumps behind the stone masonry walls on both the left and right sides of the low-level outlet.
 - The structure is located on a bedrock foundation, which appears to be stable, but there is a pool of water below the low level outlet that appears to be seepage through the structure at the interface of the stone wall with the bedrock foundation.
- Drains
 - No drains were observed.
- Instrumentation
 - No instrumentation exists at the dike.

- Access Roads and Gates
 - The dike is accessed from the dam location. It cannot be accessed directly from School Street without opening a locked gate. The gate was open at the time of the inspection.

2.1.4 Appurtenant Structures

- Primary Spillway (at Dam)
 - Water was flowing over the spillway at the time of the inspection, which prevented visual inspection of the downstream face of the spillway. Previous reports indicated minor seepage at various locations of the stone masonry structure and that the 15-inch thick concrete cap had minor surface erosion.
 - The right upstream training wall, also the upstream face at the right abutment, has horizontal and vertical transverse cracks in the wall. Pieces of concrete have fallen loose from the wall in two areas. There are no cracks in the footing.
 - The left concrete training wall has a vertical crack where a tree was growing at its base on the upstream side and spalling was observed near the top of the wall close to the spillway and along the normal pool waterline.
 - The downstream extension of the left training wall consists of boulders. These boulders are founded on bedrock. Large gaps where the boulders meet the concrete wall are allowing water to erode the embankment materials behind the wall.
 - On the right side, there is a short section of a stone masonry training wall on the downstream side. The discharge channel side slope is constructed using rubber tires to reinforce the slope for a length of approximately 80 feet. A section of the tire wall adjacent to the stone masonry appears to be sliding. A considerable number of trees that were growing on the slope within the tires have been cut but stumps remain.
- Low Level Outlet (at Dike)
 - The sluice gate is operated with a rack and pinion system and is currently inoperable. The gate is in the closed position and materials of construction are deteriorated.
 - The stop-logs within the structure were visible through the grating and show significant deterioration.
 - The structure was designed so that when the sluice gate was left in the open position, the stop logs within the outlet structure are utilized to control the impoundment level.
 - The outlet consists of a 36-inch diameter reinforced concrete pipe exiting the concrete structure.

- Metal grating exists on top of the outlet structure. The grating is secured with a keyed locking mechanism.
- The headwall at the outlet end of the 36-inch conduit consists of dry-stone masonry which is in good condition.
- The outlet channel consists of a combination of dry-stone masonry walls and stone revetment. In some locations the stones have become displaced from the walls.
- The trees that were growing downstream of the stone wall headwall and behind the outlet channel wall on both the left and right side have been cleared. The stumps remain.
- Auxiliary/Emergency Spillway
 - There is no auxiliary spillway at Forge Pond Dam.

2.1.5 Downstream Area

- Discharge from the main dam spillway flows to a natural channel and passes under School Street through three 8 x 6-foot corrugated metal pipe arch culverts.
- Discharge from the 36-inch outlet at the dike flows to a narrow, rock-lined channel and passes through a 36-inch corrugated metal pipe culvert under School Street.
- Discharge flows past the dam and dike and converges on the opposite side of School Street and continues down Bachelor Brook.
- Bachelor Brook meanders through an undeveloped area before reaching Aldrich Lake, a distance of about 21,000 feet downstream of the dam.

2.1.6 Reservoir Area

- The pond has some moderate residential development on the southerly shoreline and light residential development on the westerly shoreline. The remainder of the surrounding area is wooded hills and wetlands.

2.2 Caretaker Interview

A representative for the owner of Forge Pond Dam and Dike, was not available at the time of the inspection to provide information for this report. Lenart Consulting Service worked with the Granby DPW for permitting the recent tree removal with the Conservation Commission and Office of Dam Safety

2.3 Operation and Maintenance Procedures

2.3.1 Operational Procedures

The Town of Granby operates the dam with assistance from the Granby DPW. There are currently no formal operating procedures that are followed at Forge Pond Dam or Forge Pond Dike.

2.3.2 Maintenance of Dam and Dike

In 2019 all trees and woody vegetation on the structures and within 15 feet of any part of the structures was cleared and the grassy areas were mowed. The stumps and root systems were left in place.

There are no formal maintenance procedures for these structures. The dam is not checked on a regularly, and no records of operation are kept.

2.3.3 Emergency Warning System

A formal Emergency Action Plan has been developed for Forge Pond Dam and Dike in 2019.

2.4 Hydrologic/Hydraulic Data

Forge Pond Dam and Dike are both intermediate size, significant (Class II) hazard structures and in accordance with Massachusetts Dam Safety Regulation the spillway design flood (SDF) for the site is a 100-year flood. A Hydrologic/Hydraulic (H&H) Analysis was performed as part of the Army Corps of Engineers Phase I Inspection Report for Forge Pond Dam and Dike in 1981 and indicates that the inflow to Forge Pond during ½ PMF event is 13,230 cfs, and concluded that the spillway was inadequate without determining the design outflow from the impoundment.

The following values apply to Forge Pond Dam and Dike.

A.	Spillway Design Flood (SDF)	100-year
B.	SDF Outflow (cfs) Estimated By StreamStats	1000
C.	Spillway Capacity (cfs)	1005
D.	Depth of Overtopping	Unknown

2.5 Structural Stability/Overtopping Potential

2.5.1 Embankment Structural Stability

An embankment stability analysis for Forge Pond Dam and Dike was not within the scope of this report and there were no records of a previous stability analysis for the dam available for review. Based on visual observations at the time of the inspection, the dam and dike appear stable

2.5.2 Structural Stability of Non-Embankment Structures

A structural stability analysis of non-embankment structures for Forge Pond Dam and Dike was not within the scope of this report. At the time of the inspection, there was no indication of any concerns for structural stability of non-embankment areas

2.5.3 Seepage Stability

The 2014 visual inspection and the most recent inspection did identify minor seepage in areas along the downstream side of the dike. However, there was no indication for concerns for seepage issues observed at the structures.

2.5.4 Overtopping Potential

Based upon the Army Corps of Engineers Phase I Inspection Report for Forge Pond Dam and Dike dated 1981, it was assumed that the dam would overtop during a ½ PMF storm event. However, the design storm for the dam and dike is the 100-year storm, which is significantly smaller than a ½ PMF storm. An updated H&H Analysis should be performed to re-evaluate the overtopping potential at Forge Pond Dam and Dike.

Section 3

Assessments and Recommendations

3.1 Assessments

On the basis of the visual inspection and a review of available information, Forge Pond Dam and Forge Pond Dike are, collectively, generally in **Poor** condition. The structures were found to have the following deficiencies resulting in the condition stated:

Dam Location:

1. There is spalling, transverse structural cracks and missing pieces of concrete in the upstream training walls at both abutments.
2. The rubber tire retaining wall immediately downstream of the right end of the spillway is failing, jeopardizing the residence adjacent to the discharge channel and the right abutment.
3. Erosion of embankment soils has occurred behind the left spillway training wall at its downstream end. This condition has remained the same since the last inspection.
4. The hydraulic adequacy of the spillway to accommodate the SDF flows should be evaluated.
5. Maintenance is required including stump removal and control of woody vegetation

Dike Location:

1. The gate is not operable and materials of construction require replacement.
2. The stop-logs are deteriorated and materials of construction require replacement.

Previously Identified Deficiency	Resolution or Current Condition
Woody vegetation growing on dam abutment and on dike crest and downstream embankment	Trees and woody vegetation have been cleared. Stumps remain.
Trees growing in spillway discharge channel on left side	Trees and woody vegetation have been cleared. Stumps remain.
Concrete wall at right abutment has cracks	Cracks are slightly worse. There are also cracks in the upstream wall on the left side near spillway.
Settlement 3 feet square by 1 foot deep at right abutment	Same
During low flow, seepage was observed at stone mortar section of spillway	Unable to inspect because of flow over spillway

Seepage was observed coming through joints in bedrock at left side of spillway and from under left training wall	Unable to inspect because of flow over spillway
Some leakage past stop logs in outlet control structure	Minor leakage observed
Seepage at stone masonry/bedrock interface at downstream toe of dike	Same
Operating mechanism for low level outlet gate removed	Operating system present but inoperable and materials of construction deteriorated.
Rubber tire revetment on slope becoming undermined at toe	Soils eroded from around tires and wall leaning near spillway.

The recommendations and remedial measures that follow generally describe the recommended approach to address current deficiencies at the dam. The applicability of environmental permits should be determined prior to undertaking activities that may occur within resource areas under the jurisdiction of local conservation commissions, MADEP, or other regulatory agencies.

3.2 Studies and Analyses

The following analyses should be initiated by the Granby Conservation Commission:

1. Perform an updated, detailed Hydraulic & Hydrologic analysis to determine the design storm discharge and hydraulic adequacy of spillway.
2. Prepare a formal Operations & Maintenance Manual for the dam and the dike.

3.3 Yearly Recommendations

This section presents recommended activities that are routine maintenance.

1. Regularly mow the embankment crest and slopes to establish and maintain a good quality grass cover and to control vegetative growth.
2. Regularly remove debris from the spillway, downstream culverts and downstream channels.

3.4 Recommendations, Maintenance, and Minor Repairs

This section presents recommended activities to improve the overall condition of the dam that do not alter the current design of the dam:

1. Remove tree stumps and root systems.
2. Repair left concrete walls at the dam.
3. Fill the depressed area behind the spillway training wall at the right abutment.
4. Plant an erosion resistant surface on dam crest where soils are exposed.

The following repairs and maintenance items are recommended to improve the overall condition of the dike:

1. Remove tree stumps and root systems.
2. Repair downstream stone masonry walls
3. Monitor the leakage through the control structure. Inspect stop logs and replace when necessary.
4. Monitor seepage through the bedrock foundation under the dike.

3.5 Remedial Measures

This section presents recommended modifications to the dam that alter the current configuration or design of the structure. No remedial measures are needed at the dike at this time.

1. Repair/replace the concrete wall on the right side of the spillway.
2. Replace the tire retaining wall with a proper structure to provide stability.
3. Repair eroded area behind the left spillway training wall. Extend concrete wall or augment with rip rap.
4. Replace the materials of construction of the low-level outlet gate.
5. Replace the materials of construction of the stop logs.

3.6 Alternatives

No alternatives have been developed at this time. Design studies may provide practical alternatives to the recommendations listed above.

3.7 Opinion of Probable Costs


The following opinion of probable costs has been developed for the studies, analyses, recommendations and remedial measures noted above. Routine maintenance items that can be accomplished by Town forces are not included. The probable construction costs are based on very limited investigations. Once further detailed investigations are performed, the scope of work may change, affecting the actual construction costs. The estimates include engineering, permits and contingencies where applicable.

	Recommendation	Probable Cost
1	Prepare updated Hydraulic & Hydrologic Analysis	\$10,000
2	Develop Operations and Maintenance Manual	\$4,000
3	Remove tree stumps and root systems from embankments	\$50,000


4	Repair/replace concrete walls at the dam	\$60,000
5	Replace rubber tire wall with a more stable retaining wall	\$250,000
6	Repair eroded area behind the left spillway training wall. Augment with rip rap	\$10,000
7	Replace the materials of construction of the low-level gate and stoplogs	\$25,000
8	Repair stone masonry wall on downstream side of dike	\$10,000
	Total	\$424,000 Say \$425,000


C:\G-006\ Granbyl DCR Phase 1 Report 4/1/20\Report text.doc

Figures




USGS Quadrangle: BELCHERTOWN





USGS Quadrangle: BELCHERTOWN



APPENDIX A
Photographs

Forge Pond Dam
Forge Pond Dike

Forge Pond Dam




Photo Direction 0

DAM SITE PLAN

FORGE POND DAM

GRANBY, MA

LENART CONSULTING SERVICE, LLC
Chicopee, MA

Scale: None

Date: March 2020



Photo 1 – Downstream view of embankment left of spillway



Photo 2 – Downstream overview of dam



Photo 3 – Upstream view of embankment retaining wall cracks and spalling



Photo 4 – Upstream view of spillway from left abutment



Photo 5 – Upstream overview from right side



Photo 6 – Spillway and right training wall viewed from right side



Photo 7 – Back of left training wall and spillway crest viewed from left side



Photo 8 – Left training wall viewed from right side



Photo 9 – View of impoundment and left upstream spillway training wall



Photo 10 – View of jogged spillway crest and downstream area



Photo 11 – Right upstream training wall and tree stumps downstream of spillway at right abutment.



Photo 12 – Settlement and rotting stump behind right upstream spillway training wall



Photo 13 – Downstream side of spillway viewed from left side



Photo 14 – Left side of spillway with erosion behind left downstream training wall



Photo 15 – Downstream view of spillway from right side



Photo 16 – Spillway crest, deteriorating concrete on right training wall and upstream retaining wall



Photo 17 - Deteriorating concrete on upstream face of right spillway training wall



Photo 18 –Upstream face of right spillway training wall



Photo 19 – Upstream left retaining wall



Photo 20 – Upstream view of ACCMP culverts passing under School Street downstream

Forge Pond Dike




Photo Direction 0

DIKE SITE PLAN
FORGE POND DIKE
GRANBY, MA
LENART CONSULTING SERVICE, LLC Chicopee, MA
Scale: None Date: March 2020



Photo 1 – Overview of upstream face of dike from right abutment



Photo 2 – Upstream face viewed from right end of dike



Photo 3 – Dike crest viewed from right end



Photo 4 – Upstream face of dike from left abutment



Photo 5 – Control gate structure viewed from downstream side looking into impoundment



Photo 6 – Crest and view of left abutment



Photo 7 – Right side of rack and pinion level control gate structure



Photo 8 – Crest and low-level control structure viewed from the left side



Photo 9 – Embankment crest at right abutment



Photo 10 – Downstream slope at right side of dike



Photo 11 – Downstream stone masonry retaining wall at low level outlet



Photo 12 – Stone masonry retaining wall at discharge channel to the left of low level outlet



Photo 13 – Downstream stone retaining wall at discharge channel to the right of low level outlet



Photo 14 – Stone masonry wall on downstream slope to the left of the low-level outlet
Forge Pond Dike, Granby Date of Inspection: March 23, 2020



Photo 15 – Discharge channel viewed from the top of dike



Photo 16 – Downstream overview of the dike from School Street



Photo 17 – Downstream overview of the dike from the right side



Photo 18 – Interior of low-level outlet structure looking downstream



Photo 19 – Concrete weir in discharge channel downstream of the low-level outlet



Photo 20 – Upstream end of culvert passing under School Street downstream of low-level outlet

APPENDIX B
Inspection Checklist

Forge Pond Dam
Forge Pond Dike

Forge Pond Dam

DAM SAFETY INSPECTION CHECKLIST

NAME OF DAM: <u>Forge Pond Dam</u>		STATE ID #: <u>2-8-111-2</u>	
REGISTERED: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO		NID ID #: <u>MA00488</u>	
STATE SIZE CLASSIFICATION: <u>Intermediate</u>		STATE HAZARD CLASSIFICATION: <u>Significant</u>	
		CHANGE IN HAZARD CLASSIFICATION REQUESTED?: <u>No</u>	
<u><i>DAM LOCATION INFORMATION</i></u>			
CITY/TOWN: <u>Granby</u>		COUNTY: <u>Hampshire</u>	
DAM LOCATION: <u>School Street</u> (street address if known)		ALTERNATE DAM NAME: <u>Forge Pond Main Dam</u>	
USGS QUAD.: <u>Belchertown, MA</u>		LAT.: <u>42.274511</u> LONG.: <u>-72.47085</u>	
DRAINAGE BASIN: <u>Connecticut</u>		RIVER: <u>Bachelor Brook</u>	
IMPOUNDMENT NAME(S): <u>Forge Pond</u>			
<u><i>GENERAL DAM INFORMATION</i></u>			
TYPE OF DAM: <u>Earthen Embankment w/ concrete/masonry spillway</u>		OVERALL LENGTH (FT): <u>115</u>	
PURPOSE OF DAM: <u>Recreation</u>		NORMAL POOL STORAGE (ACRE-FT): <u>380</u>	
YEAR BUILT: <u>1900</u>		MAXIMUM POOL STORAGE (ACRE-FT): <u>600</u>	
STRUCTURAL HEIGHT (FT): <u>13.5</u>		EL. NORMAL POOL (FT): <u>271.0</u>	
HYDRAULIC HEIGHT (FT): <u>11.0</u>		EL. MAXIMUM POOL (FT): <u>273.5</u>	
<u><i>FOR INTERNAL MADCR USE ONLY</i></u>			
FOLLOW-UP INSPECTION REQUIRED: <input type="checkbox"/> YES <input type="checkbox"/> NO		CONDITIONAL LETTER: <input type="checkbox"/> YES <input type="checkbox"/> NO	

NAME OF DAM: Forge Pond Dam STATE ID #: 2-8-111-2

INSPECTION DATE: March 23, 2020 NID ID #: MA00488

INSPECTION SUMMARY

DATE OF INSPECTION: March 23, 2020 DATE OF PREVIOUS INSPECTION: July 10, 2014

TEMPERATURE/WEATHER: low 40's mostly sunny ARMY CORPS PHASE I: YES NO If YES, date March 1981

CONSULTANT: Lenart Consulting Services, LLC PREVIOUS DCR PHASE I: YES NO If YES, date _____

BENCHMARK/DATUM: USGS - 271 pond elevation set to normal pool elevation

OVERALL PHYSICAL CONDITION OF DAM: POOR DATE OF LAST REHABILITATION: 1978

SPILLWAY CAPACITY: 0-50% of the SDF or Unknown


EL. POOL DURING INSP.: 271.2 EL. TAIL WATER DURING INSP.: 262 ±

PERSONS PRESENT AT INSPECTION

NAME	TITLE/POSITION	REPRESENTING
Cathleen A. Benben	Engineer	Lenart Consulting Services, LLC

EVALUATION INFORMATION

Click on box to select E-code	
E1) TYPE OF DESIGN	3
E2) LEVEL OF MAINTENANCE	2
E3) EMERGENCY ACTION PLAN	5
E4) EMBANKMENT SEEPAGE	4
E5) EMBANKMENT CONDITION	4
E6) CONCRETE CONDITION	3
E7) LOW-LEVEL OUTLET CAPACITY	1
E8) LOW-LEVEL OUTLET CONDITION	2
E9) SPILLWAY DESIGN FLOOD CAPACITY	1
E10) OVERALL PHYSICAL CONDITION	2
E11) ESTIMATED REPAIR COST	\$375,000
ROADWAY OVER CREST	NO
BRIDGE NEAR DAM	NO

NAME OF INSPECTING ENGINEER: Cathleen A. Benben SIGNATURE: 

NAME OF DAM: <u>Forge Pond Dam</u>		STATE ID #: <u>2-8-111-2</u>	
INSPECTION DATE: <u>March 23, 2020</u>		NID ID #: <u>MA00488</u>	
OWNER: ORGANIZATION	<u>Town of Granby</u>	CARETAKER: ORGANIZATION	<u>Town of Granby</u>
NAME/TITLE	<u>Board of Selectmen</u>	NAME/TITLE	<u>Board of Selectmen</u>
STREET	<u>10B West State Street</u>	STREET	<u>10B West State Street</u>
TOWN, STATE, ZIP	<u>Granby, MA</u>	TOWN, STATE, ZIP	<u>Granby, MA</u>
PHONE	<u>(413) 467-7177</u>	PHONE	<u>(413) 467-7177</u>
EMERGENCY PH. #	<u>911</u>	EMERGENCY PH. #	<u>911</u>
FAX	<u>N/A</u>	FAX	<u>N/A</u>
EMAIL	<u>N/A</u>	EMAIL	<u>N/A</u>
OWNER TYPE	<u>Municipality or Political subdivision</u>		
PRIMARY SPILLWAY TYPE <u>Broad-crested weir, concrete and stone masonry</u>			
SPILLWAY LENGTH (FT)	<u>82</u>	SPILLWAY CAPACITY (CFS)	<u>1,005</u>
AUXILIARY SPILLWAY TYPE	<u>N/A</u>	AUX. SPILLWAY CAPACITY (CFS)	<u>N/A</u>
NUMBER OF OUTLETS	<u>1 at the dike location</u>	OUTLET(S) CAPACITY (CFS)	<u>see dike</u>
TYPE OF OUTLETS	<u>36-in. diameter conduit at the dike</u>	TOTAL DISCHARGE CAPACITY (CFS)	<u>1,091 (spillway and LLO)</u>
DRAINAGE AREA (SQ MI)	<u>14.2</u>	SPILLWAY DESIGN FLOOD (PERIOD/CFS)	<u>100-year/no H&H</u>
HAS DAM BEEN BREACHED OR OVERTOPPED	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	IF YES, PROVIDE DATE(S) _____
FISH LADDER (LIST TYPE IF PRESENT)	<u>N/A</u>		
DOES CREST SUPPORT PUBLIC ROAD?	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	IF YES, ROAD NAME: _____
PUBLIC BRIDGE WITHIN 50' OF DAM?	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	IF YES, ROAD/BRIDGE NAME: _____ MHD BRIDGE NO. (IF APPLICABLE) _____

NAME OF DAM: Forge Pond Dam

STATE ID #: 2-8-111-2

INSPECTION DATE: March 23, 2020

NID ID #: MA00488

EMBANKMENT (CREST)

AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION	MONITOR	REPAIR
CREST	1. SURFACE TYPE	Grass			X
	2. SURFACE CRACKING	None Observed	X		
	3. SINKHOLES, ANIMAL BURROWS	None Observed	X		
	4. VERTICAL ALIGNMENT (DEPRESSIONS)	Depression behind right training wall at abutment contact			X
	5. HORIZONTAL ALIGNMENT	Good	X		
	6. RUTS AND/OR PUDDLES	None Observed	X		
	7. VEGETATION (PRESENCE/CONDITION)	Grass with some exposed soils			X
	8. ABUTMENT CONTACT	Good	X		

ADDITIONAL COMMENTS: _____

NAME OF DAM: Forge Pond Dam

STATE ID #: 2-8-111-2

INSPECTION DATE: March 23, 2020

NID ID #: MA00488

EMBANKMENT (D/S SLOPE)

AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION	MONITOR	REPAIR
D/S SLOPE	1. WET AREAS (NO FLOW)	None Observed	X		
	2. SEEPAGE	None Observed	X		
	3. SLIDE, SLOUGH, SCARP	None Observed	X		
	4. EMB.-ABUTMENT CONTACT	Good on left side; interface with tire retaining wall on right side showing erosion			X
	5. SINKHOLE/ANIMAL BURROWS	None Observed	X		
	6. EROSION	Erosion behind the left spillway training wall at the downstream end			X
	7. UNUSUAL MOVEMENT	None Observed	X		
	8. VEGETATION (PRESENCE/CONDITION)	Grass cover on downstream slope sparse in areas			X
		Some areas with exposed soils where brush has been removed.			

ADDITIONAL COMMENTS: _____

NAME OF DAM: Forge Pond Dam

STATE ID #: 2-8-111-2

INSPECTION DATE: March 23, 2020

NID ID #: MA00488

EMBANKMENT (U/S SLOPE)

AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION	MONITOR	REPAIR
U/S SLOPE	1. SLIDE, SLOUGH, SCARP	N/A - Upstream face is concrete wall	X		
	2. SLOPE PROTECTION TYPE AND COND.	Concrete wall and gravel slope under water; transverse cracks and spalling			X
	3. SINKHOLE/ANIMAL BURROWS	N/A - Upstream face is concrete wall	X		
	4. EMB.-ABUTMENT CONTACT	Good	X		
	5. EROSION	N/A - Upstream face is concrete wall	X		
	6. UNUSUAL MOVEMENT	None Observed	X		
	7. VEGETATION (PRESENCE/CONDITION)	Upstream face is concrete wall,			X
		Woody vegetation growing through cracks in walls has been cut; stumps and roots			X

ADDITIONAL COMMENTS: _____

NAME OF DAM: Forge Pond Dam

STATE ID #: 2-8-111-2

INSPECTION DATE: March 23, 2020

NID ID #: MA00488

INSTRUMENTATION

AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION	MONITOR	REPAIR
INSTR.	1. PIEZOMETERS	N/A			
	2. OBSERVATION WELLS	N/A			
	3. STAFF GAGE AND RECORDER	N/A			
	4. WEIRS	N/A			
	5. INCLINOMETERS	N/A			
	6. SURVEY MONUMENTS	N/A			
	7. DRAINS	N/A			
	8. FREQUENCY OF READINGS	N/A			
	9. LOCATION OF READINGS	N/A			

ADDITIONAL COMMENTS: _____

NAME OF DAM: Forge Pond Dam

STATE ID #: 2-8-111-2

INSPECTION DATE: March 23, 2020

NID ID #: MA00488

DOWNSTREAM MASONRY WALLS

AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION	MONITOR	REPAIR	
D/S WALLS	1. WALL TYPE	N/A				
	2. WALL ALIGNMENT	N/A				
	3. WALL CONDITION	N/A				
	4. HEIGHT: TOP OF WALL TO MUDLINE	min:	max:	avg:		
	5. SEEPAGE OR LEAKAGE	N/A				
	6. ABUTMENT CONTACT	N/A				
	7. EROSION/SINKHOLES BEHIND WALL	N/A				
	8. ANIMAL BURROWS	N/A				
	9. UNUSUAL MOVEMENT	N/A				
	10. WET AREAS AT TOE OF WALL	N/A				

ADDITIONAL COMMENTS: _____

NAME OF DAM: Forge Pond Dam

STATE ID #: 2-8-111-2

INSPECTION DATE: March 23, 2020

NID ID #: MA00488

UPSTREAM MASONRY WALLS

AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION	MONITOR	REPAIR	
U/S WALLS	1. WALL TYPE	N/A				
	2. WALL ALIGNMENT	N/A				
	3. WALL CONDITION	N/A				
	4. HEIGHT: TOP OF WALL TO MUDLINE	min:	max:	avg:		
	5. ABUTMENT CONTACT	N/A				
	6. EROSION/SINKHOLES BEHIND WALL	N/A				
	7. ANIMAL BURROWS	N/A				
	8. UNUSUAL MOVEMENT	N/A				

ADDITIONAL COMMENTS: _____

NAME OF DAM: Forge Pond Dam

STATE ID #: 2-8-111-2

INSPECTION DATE: March 23, 2020

NID ID #: MA00488

DOWNSTREAM AREA

AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION	MONITOR	REPAIR
D/S AREA	1. ABUTMENT LEAKAGE	None Observed	X		
	2. FOUNDATION SEEPAGE	None Observed, previous report indicated seepage at spillway foundation		X	
	3. SLIDE, SLOUGH, SCARP	Erosion behind downstream end of spillway training wall on left			X
	4. WEIRS	None Observed	X		
	5. DRAINAGE SYSTEM	None Observed	X		
	6. INSTRUMENTATION	None Observed	X		
	7. VEGETATION	Grass cover at toe of slope. Tree stumps behind concrete training walls.			X
	8. ACCESSIBILITY	Access from School Street	X		
	9. DOWNSTREAM HAZARD DESCRIPTION	Significant - residence at right abutment, School Street 300 feet downstream			
10. DATE OF LAST EAP UPDATE	EAP 2019				

ADDITIONAL COMMENTS: _____

NAME OF DAM: Forge Pond Dam

STATE ID #: 2-8-111-2

INSPECTION DATE: March 23, 2020

NID ID #: MA00488

MISCELLANEOUS

AREA INSPECTED	CONDITION	OBSERVATIONS
MISC.	1. RESERVOIR DEPTH (AVG)	Assume 5.5
	2. RESERVOIR SHORELINE	Some development, wooded hills and marshland
	3. RESERVOIR SLOPES	Relatively flat surrounding pond
	4. ACCESS ROADS	Access is from School Street in Granby
	5. SECURITY DEVICES	Chain link fence along School Street, gated to prevent vehicular access
	6. VANDALISM OR TRESPASS	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO WHAT: public recreational use
	7. AVAILABILITY OF PLANS	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO DATE: 1977 proposed improvements
	8. AVAILABILITY OF DESIGN CALCS	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO DATE:
	9. AVAILABILITY OF EAP/LAST UPDATE	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO DATE: 2019
	10. AVAILABILITY OF O&M MANUAL	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO DATE:
	11. CARETAKER/OWNER AVAILABLE	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO DATE:
	12. CONFINED SPACE ENTRY REQUIRED	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO PURPOSE: low level control structure to access stop logs

ADDITIONAL COMMENTS: Confined space entry is required to enter low level control structure located at Forge Pond Dike

NAME OF DAM: Forge Pond Dam

STATE ID #: 2-8-111-2

INSPECTION DATE: March 23, 2020

NID ID #: MA00488

PRIMARY SPILLWAY

AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION	MONITOR	REPAIR
SPILLWAY	SPILLWAY TYPE	Stone masonry and concrete	X		
	WEIR TYPE	Broad crested	X		
	SPILLWAY CONDITION	Satisfactory - spalling observed on spillway crest		X	
	TRAINING WALLS	Fair - cracks and spalling			X
	SPILLWAY CONTROLS AND CONDITION	No control	X		
	UNUSUAL MOVEMENT	None Observed	X		
	APPROACH AREA	Concrete and riprap apron	X		
	DISCHARGE AREA	Natural stream channel, bedrock outcropping at left side. Trees have been cleared.	X		
	DEBRIS	None observed			X
	WATER LEVEL AT TIME OF INSPECTION	0.2 feet above spillway crest	X		

ADDITIONAL COMMENTS: _____

NAME OF DAM: Forge Pond Dam

STATE ID #: 2-8-111-2

INSPECTION DATE: March 23, 2020

NID ID #: MA00488

AUXILIARY SPILLWAY

AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION	MONITOR	REPAIR
SPILLWAY	SPILLWAY TYPE	N/A			
	WEIR TYPE	N/A			
	SPILLWAY CONDITION	N/A			
	TRAINING WALLS	N/A			
	SPILLWAY CONTROLS AND CONDITION	N/A			
	UNUSUAL MOVEMENT	N/A			
	APPROACH AREA	N/A			
	DISCHARGE AREA	N/A			
	DEBRIS	N/A			
	WATER LEVEL AT TIME OF INSPECTION	N/A			

ADDITIONAL COMMENTS: _____

NAME OF DAM: Forge Pond Dam

STATE ID #: 2-8-111-2

INSPECTION DATE: March 23, 2020

NID ID #: MA00488

OUTLET WORKS

AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION	MONITOR	REPAIR
OUTLET WORKS	TYPE	Concrete intake structure; gated entrance, stop logs within structure, 36-inch outlet			X
	INTAKE STRUCTURE	6 foot by 8 foot concrete structure	X		
	TRASHRACK	None	X		
	PRIMARY CLOSURE	Sluice gate upstream face	X		
	SECONDARY CLOSURE	Stop logs within structure	X		
	CONDUIT	36-inch RCP outlet	X		
	OUTLET STRUCTURE/HEADWALL	Stone masonry wall at discharge	X		
	EROSION ALONG TOE OF DAM	None	X		
	SEEPAGE/LEAKAGE	Minor leakage past gate and stop logs		X	
	DEBRIS/BLOCKAGE	None observed	X		
	UNUSUAL MOVEMENT	None observed	X		
	DOWNSTREAM AREA	Stone lined channel independent of spillway discharge channel	X		
	MISCELLANEOUS	36-inch CMP conduit crosses under School Street before convergence with spillway discharge			

ADDITIONAL COMMENTS: This structure is not located at the dam. It's location is approx. 200 feet south of the main dam at the dike.

Note: Use additional sheets for additional outlets.

NAME OF DAM: Forge Pond Dam

STATE ID #: 2-8-111-2

INSPECTION DATE: March 23, 2020

NID ID #: MA00488

CONCRETE/MASONRY DAMS

AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION	MONITOR	REPAIR
GENERAL	TYPE	N/A			
	AVAILABILITY OF PLANS	N/A			
	AVAILABILITY OF DESIGN CALCS	N/A			
	PIEZOMETERS	N/A			
	OBSERVATION WELLS	N/A			
	INCLINOMETERS	N/A			
	SEEPAGE GALLERY	N/A			
	UNUSUAL MOVEMENT	N/A			

ADDITIONAL COMMENTS: _____

NAME OF DAM: Forge Pond Dam

STATE ID #: 2-8-111-2

INSPECTION DATE: March 23, 2020

NID ID #: MA00488

CONCRETE/MASONRY DAMS (CREST)

AREA INSPECTED	CONDITION	OBSERVATIONS	NO	ACTION	MONITOR	REPAIR
CREST	TYPE	N/A				
	SURFACE CONDITIONS	N/A				
	CONDITIONS OF JOINTS	N/A				
	UNUSUAL MOVEMENT	N/A				
	HORIZONTAL ALIGNMENT	N/A				
	VERTICAL ALIGNMENT	N/A				

ADDITIONAL COMMENTS: _____

NAME OF DAM: Forge Pond Dam

STATE ID #: 2-8-111-2

INSPECTION DATE: March 23, 2020

NID ID #: MA00488

CONCRETE/MASONRY DAMS (DOWNSTREAM FACE)

AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION	MONITOR	REPAIR
D/S FACE	TYPE	N/A			
	SURFACE CONDITIONS	N/A			
	CONDITIONS OF JOINTS	N/A			
	UNUSUAL MOVEMENT	N/A			
	ABUTMENT CONTACT	N/A			
	LEAKAGE	N/A			

ADDITIONAL COMMENTS: _____

NAME OF DAM: Forge Pond Dam

STATE ID #: 2-8-111-2

INSPECTION DATE: March 23, 2020

NID ID #: MA00488

CONCRETE/MASONRY DAMS (UPSTREAM FACE)

AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION	MONITOR	REPAIR
U/S FACE	TYPE	N/A			
	SURFACE CONDITIONS	N/A			
	CONDITIONS OF JOINTS	N/A			
	UNUSUAL MOVEMENT	N/A			
	ABUTMENT CONTACTS	N/A			

ADDITIONAL COMMENTS: _____

Forge Pond Dike

DAM SAFETY INSPECTION CHECKLIST


NAME OF DAM: <u>Forge Pond Dike</u>	STATE ID #: <u>2-8-111-3</u>
REGISTERED: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	NID ID #: <u>MA00489</u>
STATE SIZE CLASSIFICATION: <u>Intermediate</u>	STATE HAZARD CLASSIFICATION: <u>Significant</u>
	CHANGE IN HAZARD CLASSIFICATION REQUESTED?: <u>No</u>
<u>DAM LOCATION INFORMATION</u>	
CITY/TOWN: <u>Granby</u>	COUNTY: <u>Hampshire</u>
DAM LOCATION: <u>School Street</u> (street address if known)	ALTERNATE DAM NAME: <u>Forge Pond Small Dam</u>
USGS QUAD.: <u>Belchertown, MA</u>	LAT.: <u>42.273763</u> LONG.: <u>-72.470885</u>
DRAINAGE BASIN: <u>Connecticut</u>	RIVER: <u>Bachelor Brook</u>
IMPOUNDMENT NAME(S): <u>Forge Pond</u>	
<u>GENERAL DAM INFORMATION</u>	
TYPE OF DAM: <u>Earthen Embankment w/ stone masonry upstream face</u>	OVERALL LENGTH (FT): <u>90</u>
PURPOSE OF DAM: <u>Recreation</u>	NORMAL POOL STORAGE (ACRE-FT): <u>320</u>
YEAR BUILT: <u>1800</u>	MAXIMUM POOL STORAGE (ACRE-FT): <u>540</u>
STRUCTURAL HEIGHT (FT): <u>10.7</u>	EL. NORMAL POOL (FT): <u>271.0</u>
HYDRAULIC HEIGHT (FT): <u>8.2</u>	EL. MAXIMUM POOL (FT): <u>273.5</u>
<u>FOR INTERNAL MADCR USE ONLY</u>	
FOLLOW-UP INSPECTION REQUIRED: <input type="checkbox"/> YES <input type="checkbox"/> NO	CONDITIONAL LETTER: <input type="checkbox"/> YES <input type="checkbox"/> NO

NAME OF DAM: Forge Pond Dike STATE ID #: 2-8-111-3
 INSPECTION DATE: March 23, 2020 NID ID #: MA00489
INSPECTION SUMMARY
 DATE OF INSPECTION: March 23, 2020 DATE OF PREVIOUS INSPECTION: July 10, 2020
 TEMPERATURE/WEATHER: lower 50's and sxunny ARMY CORPS PHASE I: YES NO If YES, date March 1981
 CONSULTANT: Lenart Consulting Services, LLC PREVIOUS DCR PHASE I: YES NO If YES, date _____
 BENCHMARK/DATUM: USGS
 OVERALL PHYSICAL CONDITION OF DAM: POOR DATE OF LAST REHABILITATION: 1978
 SPILLWAY CAPACITY: No spillway at dike EL. TAILWATER DURING INSP.: 263.3 ±
PERSONS PRESENT AT INSPECTION

NAME	TITLE/POSITION	REPRESENTING
Cathy Benben	Engineer	Lenart Consulting Services, LLC

EVALUATION INFORMATION

Click on box to select E-code	
E1) TYPE OF DESIGN	3
E2) LEVEL OF MAINTENANCE	2
E3) EMERGENCY ACTION PLAN	5
E4) EMBANKMENT SEEPAGE	4
E5) EMBANKMENT CONDITION	3
E6) CONCRETE CONDITION	4
E7) LOW-LEVEL OUTLET CAPACITY	2
E8) LOW-LEVEL OUTLET CONDITION	2
E9) SPILLWAY DESIGN FLOOD CAPACITY	1
E10) OVERALL PHYSICAL CONDITION	2
E11) ESTIMATED REPAIR COST	\$50,000
ROADWAY OVER CREST	NO
BRIDGE NEAR DAM	NO

 NAME OF INSPECTING ENGINEER: Cathleen A. Benben SIGNATURE: 

NAME OF DAM: <u>Forge Pond Dike</u>		STATE ID #: <u>2-8-111-3</u>	
INSPECTION DATE: <u>March 23, 2020</u>		NID ID #: <u>MA00489</u>	
OWNER: ORGANIZATION	<u>Town of Granby</u>	CARETAKER: ORGANIZATION	<u>Town of Granby</u>
NAME/TITLE	<u>Board of Selectmen</u>	NAME/TITLE	<u>Board of Selectmen</u>
STREET	<u>10B West Stae Street</u>	STREET	<u>10B West State Street</u>
TOWN, STATE, ZIP	<u>Granby, MA</u>	TOWN, STATE, ZIP	<u>Granby, MA</u>
PHONE	<u>(413) 467-7177</u>	PHONE	<u>(413) 467-7177</u>
EMERGENCY PH. #	<u>911</u>	EMERGENCY PH. #	<u>911</u>
FAX	<u></u>	FAX	<u></u>
EMAIL	<u></u>	EMAIL	<u></u>
OWNER TYPE	<u>Municipality or Political subdivision</u>		
PRIMARY SPILLWAY TYPE <u>located at dam</u>			
SPILLWAY LENGTH (FT) <u>see dam</u>		SPILLWAY CAPACITY (CFS) <u>see dam data</u>	
AUXILIARY SPILLWAY TYPE <u>N/A</u>		AUX. SPILLWAY CAPACITY (CFS) <u>N/A</u>	
NUMBER OF OUTLETS <u>1</u>		OUTLET(S) CAPACITY (CFS) <u>86</u>	
TYPE OF OUTLETS <u>36-inch RCP conduit</u>		TOTAL DISCHARGE CAPACITY (CFS) <u>1,091 (spillway and LLO)</u>	
DRAINAGE AREA (SQ MI) <u>14.2</u>		SPILLWAY DESIGN FLOOD (PERIOD/CFS) <u>100-yr/unknown</u>	
HAS DAM BEEN BREACHED OR OVERTOPPED <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO IF YES, PROVIDE DATE(S) _____			
FISH LADDER (LIST TYPE IF PRESENT) <u>N/A</u>			
DOES CREST SUPPORT PUBLIC ROAD? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		IF YES, ROAD NAME: _____	
PUBLIC BRIDGE WITHIN 50' OF DAM? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		IF YES, ROAD/BRIDGE NAME: _____	
MHD BRIDGE NO. (IF APPLICABLE) _____			

NAME OF DAM: Forge Pond Dike

STATE ID #: 2-8-111-3

INSPECTION DATE: March 23, 2020

NID ID #: MA00489

EMBANKMENT (CREST)

AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION	MONITOR	REPAIR
CREST	1. SURFACE TYPE	Grass	X		
	2. SURFACE CRACKING	None observed	X		
	3. SINKHOLES, ANIMAL BURROWS	None observed	X		
	4. VERTICAL ALIGNMENT (DEPRESSIONS)	Good, minor depression behind upstream wall from foot traffic wear	X		
	5. HORIZONTAL ALIGNMENT	Good	X		
	6. RUTS AND/OR PUDDLES	None observed	X		
	7. VEGETATION (PRESENCE/CONDITION)	Grass and woody vegetation recently cut		X	
	8. ABUTMENT CONTACT	Good		X	

ADDITIONAL COMMENTS: _____

NAME OF DAM: Forge Pond Dike

STATE ID #: 2-8-111-3

INSPECTION DATE: March 23, 2020

NID ID #: MA00489

EMBANKMENT (D/S SLOPE)

AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION	MONITOR	REPAIR
D/S SLOPE	1. WET AREAS (NO FLOW)	Shallow pool of water below LLO discharge		X	
	2. SEEPAGE	Some leakage below interface of stone masonry wall and bedrock		X	
	3. SLIDE, SLOUGH, SCARP	None observed	X		
	4. EMB.-ABUTMENT CONTACT	Good		X	
	5. SINKHOLE/ANIMAL BURROWS	None observed	X		
	6. EROSION	None observed		X	
	7. UNUSUAL MOVEMENT	None observed	X		
	8. VEGETATION (PRESENCE/CONDITION)	Grass cover on right downstream slope			X
		Trees that were growing adjacent to the stone masonry walls and along left embankment			X
		have been cut. Stumps remain			

ADDITIONAL COMMENTS: _____

NAME OF DAM: Forge Pond Dike

STATE ID #: 2-8-111-3

INSPECTION DATE: March 23, 2020

NID ID #: MA00489

EMBANKMENT (U/S SLOPE)

AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION	MONITOR	REPAIR
U/S SLOPE	1. SLIDE, SLOUGH, SCARP	Upstream face is concrete and stone masonry wall		X	
	2. SLOPE PROTECTION TYPE AND COND.	N/A-Upstream face is stone masonry	X		
	3. SINKHOLE/ANIMAL BURROWS	N/A-Upstream face is stone masonry	X		
	4. EMB.-ABUTMENT CONTACT	Good	X		
	5. EROSION	N/A-Upstream face is stone masonry	X		
	6. UNUSUAL MOVEMENT	None observed		X	
	7. VEGETATION (PRESENCE/CONDITION)	Upstream face is stone masonry	X		

ADDITIONAL COMMENTS: _____

NAME OF DAM: Forge Pond Dike

STATE ID #: 2-8-111-3

INSPECTION DATE: March 23, 2020

NID ID #: MA00489

INSTRUMENTATION

AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION	MONITOR	REPAIR
INSTR.	1. PIEZOMETERS	N/A			
	2. OBSERVATION WELLS	N/A			
	3. STAFF GAGE AND RECORDER	N/A			
	4. WEIRS	N/A			
	5. INCLINOMETERS	N/A			
	6. SURVEY MONUMENTS	N/A			
	7. DRAINS	N/A			
	8. FREQUENCY OF READINGS	N/A			
	9. LOCATION OF READINGS	N/A			

ADDITIONAL COMMENTS: _____

NAME OF DAM: Forge Pond Dike

STATE ID #: 2-8-111-3

INSPECTION DATE: March 23, 2020

NID ID #: MA00489

DOWNSTREAM MASONRY WALLS

AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION	MONITOR	REPAIR
D/S WALLS	1. WALL TYPE	Stone masonry wall downstream of LLO and on left embankment		X	
	2. WALL ALIGNMENT	Good -Wall is curved left of outlet location	X		
	3. WALL CONDITION	2-foot section collapsed, wall only 2 feet high			X
	4. HEIGHT: TOP OF WALL TO MUDLINE	min: 1.5 ft max: 2.5 ft avg: 2 ft	X		
	5. SEEPAGE OR LEAKAGE	None observed-mostly above normal pool-near left abutment	X		
	6. ABUTMENT CONTACT	Good	X		
	7. EROSION/SINKHOLES BEHIND WALL	None observed	X		
	8. ANIMAL BURROWS	None observed	X		
	9. UNUSUAL MOVEMENT	2-foot section collapsed, no embankment movement			X
	10. WET AREAS AT TOE OF WALL	Minor seepage noted at base of wall near outlet		X	

ADDITIONAL COMMENTS: Trees and woody vegetation that was growing adjacent to, and behind stone masonry walls has been cut. Stumps remain

NAME OF DAM: Forge Pond Dike

STATE ID #: 2-8-111-3

INSPECTION DATE: March 23, 2020

NID ID #: MA00489

UPSTREAM MASONRY WALLS

AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION	MONITOR	REPAIR
U/S WALLS	1. WALL TYPE	Mortared stone masonry	X		
	2. WALL ALIGNMENT	Straight, good alignment	X		
	3. WALL CONDITION	Good	X		
	4. HEIGHT: TOP OF WALL TO MUDLINE	min: est. 4 max: 7.5 avg: est. 6.0	X		
	5. ABUTMENT CONTACT	Good	X		
	6. EROSION/SINKHOLES BEHIND WALL	None observed		X	
	7. ANIMAL BURROWS	None observed		X	
	8. UNUSUAL MOVEMENT	None observed		X	

ADDITIONAL COMMENTS: _____

NAME OF DAM: Forge Pond Dike

STATE ID #: 2-8-111-3

INSPECTION DATE: March 23, 2020

NID ID #: MA00489

DOWNSTREAM AREA

AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION	MONITOR	REPAIR
D/S AREA	1. ABUTMENT LEAKAGE	None observed	X		
	2. FOUNDATION SEEPAGE	Some seepage at location of low level outlet below interface with bedrock		X	
	3. SLIDE, SLOUGH, SCARP	None observed	X		
	4. WEIRS	There is a concrete weir in the downstream channel - remove weir			X
	5. DRAINAGE SYSTEM	None observed	X		
	6. INSTRUMENTATION	None observed	X		
	7. VEGETATION	Trees and brush that were lining the downstream channel have been cut			X
	8. ACCESSIBILITY	The dike accessible by foot from the dam and through a locked gate off of School St.	X		
9. DOWNSTREAM HAZARD DESCRIPTION	Significant - If the dike were to fail, or overtop, flow would be restricted by the culvert crossing under School Street				
10. DATE OF LAST EAP UPDATE			2019		

ADDITIONAL COMMENTS: _____

NAME OF DAM: Forge Pond Dike

STATE ID #: 2-8-111-3

INSPECTION DATE: March 23, 2020

NID ID #: MA00489

MISCELLANEOUS

AREA INSPECTED	CONDITION	OBSERVATIONS
MISC.	1. RESERVOIR DEPTH (AVG)	Assume 5.5
	2. RESERVOIR SHORELINE	Some development, wooded hills and marshland
	3. RESERVOIR SLOPES	Relatively flat surrounding pond
	4. ACCESS ROADS	Access is from School Street in Granby
	5. SECURITY DEVICES	Chain link fence along School Street, gated to prevent vehicular access
	6. VANDALISM OR TRESPASS	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO WHAT: public recreational use
	7. AVAILABILITY OF PLANS	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO DATE: 1977 proposed improvements
	8. AVAILABILITY OF DESIGN CALCS	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO DATE:
	9. AVAILABILITY OF EAP/LAST UPDATE	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO DATE: 2019
	10. AVAILABILITY OF O&M MANUAL	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO DATE:
	11. CARETAKER/OWNER AVAILABLE	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO DATE:
	12. CONFINED SPACE ENTRY REQUIRED	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO PURPOSE: low level control structure to access stop logs

ADDITIONAL COMMENTS: _____

NAME OF DAM: Forge Pond Dike

STATE ID #: 2-8-111-3

INSPECTION DATE: March 23, 2020

NID ID #: MA00489

PRIMARY SPILLWAY

AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION	MONITOR	REPAIR
SPILLWAY	SPILLWAY TYPE	N/A			
	WEIR TYPE	N/A			
	SPILLWAY CONDITION	N/A			
	TRAINING WALLS	N/A	PRIMARY SPILLWAY LOCATED 200 FEET TO THE NORTH AT THE		
	SPILLWAY CONTROLS AND CONDITION	N/A	MAIN DAM		
	UNUSUAL MOVEMENT	N/A			
	APPROACH AREA	N/A			
	DISCHARGE AREA	N/A			
	DEBRIS	N/A			
	WATER LEVEL AT TIME OF INSPECTION	N/A			

ADDITIONAL COMMENTS: _____

NAME OF DAM: Forge Pond Dike

STATE ID #: 2-8-111-3

INSPECTION DATE: March 23, 2020

NID ID #: MA00489

AUXILIARY SPILLWAY

AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION	MONITOR	REPAIR
SPILLWAY	SPILLWAY TYPE	N/A			
	WEIR TYPE	N/A			
	SPILLWAY CONDITION	N/A			
	TRAINING WALLS	N/A			
	SPILLWAY CONTROLS AND CONDITION	N/A			
	UNUSUAL MOVEMENT	N/A			
	APPROACH AREA	N/A			
	DISCHARGE AREA	N/A			
	DEBRIS	N/A			
	WATER LEVEL AT TIME OF INSPECTION	N/A			

ADDITIONAL COMMENTS: _____

NAME OF DAM: Forge Pond Dike

STATE ID #: 2-8-111-3

INSPECTION DATE: March 23, 2020

NID ID #: MA00489

OUTLET WORKS

AREA INSPECTED	CONDITION	OBSERVATIONS			
			NO ACTION	MONITOR	REPAIR
OUTLET WORKS	TYPE	Concrete intake structure, sluice gate, stop logs within structure, 36-in outlet			X
	INTAKE STRUCTURE	6 foot by 8 foot concrete structure	X		
	TRASHRACK	None	X		
	PRIMARY CLOSURE	Sluice gate upstream face			X
	SECONDARY CLOSURE	Stop logs within structure			X
	CONDUIT	36-inch RCP outlet	X		
	OUTLET STRUCTURE/HEADWALL	Stone masonry wall at discharge	X		
	EROSION ALONG TOE OF DAM	None	X		
	SEEPAGE/LEAKAGE	Minor leakage past gate and stop logs	X		
	DEBRIS/BLOCKAGE	None observed	X		
	UNUSUAL MOVEMENT	None observed	X		
	DOWNSTREAM AREA	Stone lined channel independent of spillway discharge channel	X		
	MISCELLANEOUS	36-inch CMP conduit crosses under School Street before convergence with spillway discharge	X		

ADDITIONAL COMMENTS: _____

Note: Use additional sheets for additional outlets.

NAME OF DAM: Forge Pond Dike

STATE ID #: 2-8-111-3

INSPECTION DATE: March 23, 2020

NID ID #: MA00489

CONCRETE/MASONRY DAMS

AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION	MONITOR	REPAIR
GENERAL	TYPE	N/A			
	AVAILABILITY OF PLANS	N/A			
	AVAILABILITY OF DESIGN CALCS	N/A			
	PIEZOMETERS	N/A			
	OBSERVATION WELLS	N/A			
	INCLINOMETERS	N/A			
	SEEPAGE GALLERY	N/A			
	UNUSUAL MOVEMENT	N/A			
		N/A			

ADDITIONAL COMMENTS: _____

NAME OF DAM: Forge Pond Dike

STATE ID #: 2-8-111-3

INSPECTION DATE: March 23, 2020

NID ID #: MA00489

CONCRETE/MASONRY DAMS (CREST)

AREA INSPECTED	CONDITION	OBSERVATIONS	NO	ACTION	MONITOR	REPAIR	
CREST	TYPE	N/A					
	SURFACE CONDITIONS	N/A					
	CONDITIONS OF JOINTS	N/A					
	UNUSUAL MOVEMENT	N/A					
	HORIZONTAL ALIGNMENT	N/A					
	VERTICAL ALIGNMENT	N/A					

ADDITIONAL COMMENTS: _____

NAME OF DAM: Forge Pond Dike

STATE ID #: 2-8-111-3

INSPECTION DATE: March 23, 2020

NID ID #: MA00489

CONCRETE/MASONRY DAMS (DOWNSTREAM FACE)

AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION	MONITOR	REPAIR
D/S FACE	TYPE	Dry stone masonry wall at location of LLO		X	
	SURFACE CONDITIONS	Wall surface not flat; tree stumps adjacent to wall			X
	CONDITIONS OF JOINTS	Dry stone masonry		X	
	UNUSUAL MOVEMENT	Minor movement; wall surface not flat		X	
	ABUTMENT CONTACT	N/A			
	LEAKAGE	Minor seepage at interface with bedrock		X	

ADDITIONAL COMMENTS: _____

NAME OF DAM: Forge Pond Dike

STATE ID #: 2-8-111-3

INSPECTION DATE: March 23, 2020

NID ID #: MA00489

CONCRETE/MASONRY DAMS (UPSTREAM FACE)

AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION	MONITOR	REPAIR
U/S FACE	TYPE	Dike is earthen embankment with stone masonry on upstream face	X		
	SURFACE CONDITIONS	Good above the water line	X		
	CONDITIONS OF JOINTS	Good above the water line	X		
	UNUSUAL MOVEMENT	None observed	X		
	ABUTMENT CONTACTS	Good		X	

ADDITIONAL COMMENTS: _____

APPENDIX C
Previous Reports and References

PREVIOUS REPORTS AND REFERENCES

The following is a list of reports that were referenced in the previous report.

1. *Phase I Inspection/Evaluation Report for Forge Pond Dam and Dike, prepared by Lenart Consulting Service, LLC., dated July 10, 2014*
2. *Phase I Inspection/Evaluation Report for Forge Pond Dam and Dike, prepared by Tighe & Bond, Inc., dated April 17, 2009.*
3. *Phase I Inspection Report, National Dam Inspection Program, for Forge Pond Dam and Dike MA00488 and MA00489, prepared for the Department of the Army Corps of Engineers by Culligan Engineering Co. Inc., dated March 4, 1981.*
4. *Plans for Proposed Repairs and Restoration Work at Forge Pond Dam and Dike prepared by MGS Michael G. Suprenant, Consulting Engineer, dated October 1977.*
5. *Letter from DEQE, Division of Waterways to the Town of Granby ordering the Town to repair, or remove, the Forge Pond Dike, dated March 8, 1977.*
6. *Letter from DEQE, Division of Waterways to the Town of Granby declaring that the Forge Pond Dike was unsafe, dated September 26, 1977.*
7. *Inspection Report for Forge Pond Main Dam prepared by the Department of Public works, dated August 26, 1975.*
8. *Inspection Report for Forge Pond Main Dam prepared by the Department of Public works, dated July 23, 1973.*

APPENDIX D
Definitions

COMMON DAM SAFETY DEFINITIONS

To provide a better understanding of this report, definitions of commonly used terms associated with dams are provided below. The terms are presented under the following common categories:

- 1) Orientation;
- 2) Dam components;
- 3) Size classification;
- 4) Hazard classification; and
- 5) General.

Orientation

Upstream – Shall mean the side of the dam that borders the impoundment.

Downstream – Shall mean the high side of the dam, the side opposite the upstream side.

Right – Shall mean the area to the right when looking in the downstream direction.

Left – Shall mean the area to the left when looking in the downstream direction.

Dam Components

Dam/Dike – Shall mean any artificial barrier, including appurtenant works, which impounds or diverts water.

Embankment – Shall mean the fill material, usually earth or rock, placed with sloping sides, such that it forms a barrier that impounds water.

Crest – Shall mean the top of the dam, usually provides a road or path across the dam.

Abutment – Shall mean the top of the dam, usually provides a road or path across the dam.

Appurtenant Works – Shall mean any ancillary feature of a dam and shall include but not be limited to, such structures as training walls, spillways, either in the dam or separate there from and low level outlet works; also water conduits such as tunnels, channels, pipelines, or penstocks, either through the dam or its abutments.

Riprap – Shall mean a loose assemblage of broken stones erected in water or soft ground as erosion protection.

Toe – Shall mean the protruding base of the dam on the downstream side either natural or man-made.

Weir – Shall mean the top of the spillway where the water flows to the downstream side

Size Classification

(as listed in Commonwealth of Massachusetts, 302 CMR *Dam Safety Rules and Regulations*, revised 11/04/05)

Large – Structure with a height greater than 40 feet and/or a storage capacity greater than 1,000 acre-feet.

Intermediate – Structure with a height between 15 and 40 feet and/or a storage capacity of 50 to 1,000 acre-feet.

Small – Structure with a height between 6 and 15 feet and/or a storage capacity of 15 to 50 acre-feet.

Non-Jurisdictional – Structure less than 6 feet in height and having a storage capacity of less than 15 acre-feet.

Hazard Classification

(as listed in Commonwealth of Massachusetts, 302 CMR *Dam Safety Rules and Regulations*, revised 11/04/05)

High Hazard (Class I) – Shall mean dams/dikes located where failure or misoperation will likely cause loss of life and/or serious damage to homes, industrial or commercial facilities, important public utilities, or major transportation arteries.

Significant Hazard (Class II) – Shall mean dams/dikes located where failure or misoperation may cause loss of life and/or damage to homes, industrial or commercial facilities, secondary highways or railroads, or cause the interruption of the use or service of important facilities.

Low Hazard (Class III) – Dams/dikes located where failure or misoperation may cause minimal property damage to others and loss of life is not expected.

General

DCR – Department of Conservation and Recreation, formerly the Department of Environmental Management (DEM).

EAP – Emergency Action Plan; shall mean a predetermined plan of action to be taken to reduce the potential for property damage and/or loss of life in an area affected by an impending dam break.

O&M Manual – Operations and Maintenance Manual; document identifying routine maintenance and operational procedures under normal and storm conditions.

Normal Pool – shall mean the elevation of the impoundment during normal operating conditions.

Acre-foot – shall mean a volume equal to one foot of water over a one-acre area.

Height of Dam/Dike – shall mean the vertical distance from the lowest portion of the natural ground, including any stream channel, along the downstream toe of the dam to the crest of the dam/dike.

Spillway Design Flood (SDF) – shall mean the flood used in the design of a dam and its appurtenant works particularly for sizing the spillway and outlet works.

APPENDIX D
Definitions

COMMON DAM SAFETY DEFINITIONS

To provide a better understanding of this report, definitions of commonly used terms associated with dams are provided below. The terms are presented under the following common categories:

- 1) Orientation;
- 2) Dam components;
- 3) Size classification;
- 4) Hazard classification; and
- 5) General.

Orientation

Upstream – Shall mean the side of the dam that borders the impoundment.

Downstream – Shall mean the high side of the dam, the side opposite the upstream side.

Right – Shall mean the area to the right when looking in the downstream direction.

Left – Shall mean the area to the left when looking in the downstream direction.

Dam Components

Dam/Dike – Shall mean any artificial barrier, including appurtenant works, which impounds or diverts water.

Embankment – Shall mean the fill material, usually earth or rock, placed with sloping sides, such that it forms a barrier that impounds water.

Crest – Shall mean the top of the dam, usually provides a road or path across the dam.

Abutment – Shall mean the top of the dam, usually provides a road or path across the dam.

Appurtenant Works – Shall mean any ancillary feature of a dam and shall include but not be limited to, such structures as training walls, spillways, either in the dam or separate there from and low level outlet works; also water conduits such as tunnels, channels, pipelines, or penstocks, either through the dam or its abutments.

Riprap – Shall mean a loose assemblage of broken stones erected in water or soft ground as erosion protection.

Toe – Shall mean the protruding base of the dam on the downstream side either natural or man-made.

Weir – Shall mean the top of the spillway where the water flows to the downstream side

Size Classification

(as listed in Commonwealth of Massachusetts, 302 CMR *Dam Safety Rules and Regulations*, revised 11/04/05)

Large – Structure with a height greater than 40 feet and/or a storage capacity greater than 1,000 acre-feet.

Intermediate – Structure with a height between 15 and 40 feet and/or a storage capacity of 50 to 1,000 acre-feet.

Small – Structure with a height between 6 and 15 feet and/or a storage capacity of 15 to 50 acre-feet.

Non-Jurisdictional – Structure less than 6 feet in height and having a storage capacity of less than 15 acre-feet.

Hazard Classification

(as listed in Commonwealth of Massachusetts, 302 CMR *Dam Safety Rules and Regulations*, revised 11/04/05)

High Hazard (Class I) – Shall mean dams/dikes located where failure or misoperation will likely cause loss of life and/or serious damage to homes, industrial or commercial facilities, important public utilities, or major transportation arteries.

Significant Hazard (Class II) – Shall mean dams/dikes located where failure or misoperation may cause loss of life and/or damage to homes, industrial or commercial facilities, secondary highways or railroads, or cause the interruption of the use or service of important facilities.

Low Hazard (Class III) – Dams/dikes located where failure or misoperation may cause minimal property damage to others and loss of life is not expected.

General

DCR – Department of Conservation and Recreation, formerly the Department of Environmental Management (DEM).

EAP – Emergency Action Plan; shall mean a predetermined plan of action to be taken to reduce the potential for property damage and/or loss of life in an area affected by an impending dam break.

O&M Manual – Operations and Maintenance Manual; document identifying routine maintenance and operational procedures under normal and storm conditions.

Normal Pool – shall mean the elevation of the impoundment during normal operating conditions.

Acre-foot – shall mean a volume equal to one foot of water over a one-acre area.

Height of Dam/Dike – shall mean the vertical distance from the lowest portion of the natural ground, including any stream channel, along the downstream toe of the dam to the crest of the dam/dike.

Spillway Design Flood (SDF) – shall mean the flood used in the design of a dam and its appurtenant works particularly for sizing the spillway and outlet works.