

Outfall Catchment System Vulnerability Factor (SVF) Inventory  
Granby, Massachusetts

Revision Date: January 28, 2021

Outfall ID	Catchment ID	1	2	3	4	5	6	7	8
		History of SSOs	Common or Twin Invert Manholes	Common Trench Construction	Storm/Sanitary Crossings (Sanitary Above)	Sanitary Lines with Underdrains	Inadequate Sanitary Level of Service	Areas Formerly Served by Combined Sewers	Sanitary Infrastructure Defects
1	1	No	No	No	No	No	No	No	No
2	2	No	No	No	No	No	No	No	No
3	3	No	No	No	No	No	No	No	No
4	4	No	No	No	No	No	No	No	No
5	5	No	No	No	No	No	No	No	No
6	6	No	No	No	No	No	No	No	No
7	7	No	No	No	No	No	No	No	No
8	8	No	No	No	No	No	No	No	No
9	9	No	No	No	No	No	No	No	No
10	10	No	No	No	No	No	No	No	No
11	11	No	No	No	No	No	No	No	No
12	12	No	No	No	No	No	No	No	No
13	13	No	No	No	No	No	No	No	No
14	14	No	No	No	No	No	No	No	No
15	15	No	No	No	No	No	No	No	No
16	16	No	No	No	No	No	No	No	No
17	17	No	No	No	No	No	No	No	No
18	18	No	No	No	No	No	No	No	No
19	19	No	No	No	No	No	No	No	No
20	20	No	No	No	No	No	No	No	No
21	21	No	No	No	No	No	No	No	No
22	22	No	No	No	No	No	No	No	No
24	24	No	No	No	No	No	No	No	No
25	25	No	No	No	No	No	No	No	No
26	26	No	No	No	No	No	No	No	No
28	28	No	No	No	No	No	No	No	No
29	29	No	No	No	No	No	No	No	No
30	30	No	No	No	No	No	No	No	No
31	31	No	No	No	No	No	No	No	No

Outfall Catchment System Vulnerability Factor (SVF) Inventory

Granby, Massachusetts

Revision Date: January 28, 2021

32	32	No	No	No	No	No	No	No	No	No
33	33	No	No	No	No	No	No	No	No	No
34	34	No	No	No	No	No	No	No	No	No
35	35	No	No	No	No	No	No	No	No	No
36	36	No	No	No	No	No	No	No	No	No
37	37	No	No	No	No	No	No	No	No	No
38	38	No	No	No	No	No	No	No	No	No
39	39	No	No	No	No	No	No	No	No	No
40	40	No	No	No	No	No	No	No	No	No
41	41	No	No	No	No	No	No	No	No	No
42	42	No	No	No	No	No	No	No	No	No
43	43	No	No	No	No	No	No	No	No	No
44	44	No	No	No	No	No	No	No	No	No
45	45	No	No	No	No	No	No	No	No	No
46	46	No	No	No	No	No	No	No	No	No
47	47	No	No	No	No	No	No	No	No	No
48	48	No	No	No	No	No	No	No	No	No
49	49	No	No	No	No	No	No	No	No	No
50	50	No	No	No	No	No	No	No	No	No
51	51	No	No	No	No	No	No	No	No	No
52	52	No	No	No	No	No	No	No	No	No
53	53	No	No	No	No	No	No	No	No	No
54	54	No	No	No	No	No	No	No	No	No
55	55	No	No	No	No	No	No	No	No	No
56	56	No	No	No	No	No	No	No	No	No
57	57	No	No	No	No	No	No	No	No	No
58	58	No	No	No	No	No	No	No	No	No
59	59	No	No	No	No	No	No	No	No	No
61	61	No	No	No	No	No	No	No	No	No
62	62	No	No	No	No	No	No	No	No	No
63	63	No	No	No	No	No	No	No	No	No
64	64	No	No	No	No	No	No	No	No	No
65	65	No	No	No	No	No	No	No	No	No

Outfall Catchment System Vulnerability Factor (SVF) Inventory

Granby, Massachusetts

Revision Date: January 28, 2021

66	66	No	No	No	No	No	No	No	No
67	67	No	No	No	No	No	No	No	No
68	68	No	No	No	No	No	No	No	No
69	69	No	No	No	No	No	No	No	No
70	70	No	No	No	No	No	No	No	No
71	71	No	No	No	No	No	No	No	No
72	72	No	No	No	No	No	No	No	No
73	73	No	No	No	No	No	No	No	No
74	74	No	No	No	No	No	No	No	No
75	75	No	No	No	No	No	No	No	No
76	76	No	No	No	No	No	No	No	No
77	77	No	No	No	No	No	No	No	No
78	78	No	No	No	No	No	No	No	No
79	79	No	No	No	No	No	No	No	No
80	80	No	No	No	No	No	No	No	No
81	81	No	No	No	No	No	No	No	No
82	82	No	No	No	No	No	No	No	No
83	83	No	No	No	No	No	No	No	No
84	84	No	No	No	No	No	No	No	No
85	85	No	No	No	No	No	No	No	No
86	86	No	No	No	No	No	No	No	No
87	87	No	No	No	No	No	No	No	No
88	88	No	No	No	No	No	No	No	No
89	89	No	No	No	No	No	No	No	No
90	90	No	No	No	No	No	No	No	No
91	91	No	No	No	No	No	No	No	No
92	92	No	No	No	No	No	No	No	No
93	93	No	No	No	No	No	No	No	No
94	94	No	No	No	No	No	No	No	No
95	95	No	No	No	No	No	No	No	No
96	96	No	No	No	No	No	No	No	No
97	97	No	No	No	No	No	No	No	No
98	98	No	No	No	No	No	No	No	No

Outfall Catchment System Vulnerability Factor (SVF) Inventory

Granby, Massachusetts

Revision Date: January 28, 2021

99	99	No	No	No	No	No	No	No	No
100	100	No	No	No	No	No	No	No	No
101	101	No	No	No	No	No	No	No	No
102	102	No	No	No	No	No	No	No	No
103	103	No	No	No	No	No	No	No	No
104	104	No	No	No	No	No	No	No	No
105	105	No	No	No	No	No	No	No	No
106	106	No	No	No	No	No	No	No	No
107	107	No	No	No	No	No	No	No	No
108	108	No	No	No	No	No	No	No	No
109	109	No	No	No	No	No	No	No	No
110	110	No	No	No	No	No	No	No	No
111	111	No	No	No	No	No	No	No	No
112	112	No	No	No	No	No	No	No	No
113	113	No	No	No	No	No	No	No	No
114	114	No	No	No	No	No	No	No	No
115	115	No	No	No	No	No	No	No	No
116	116	No	No	No	No	No	No	No	No
117	117	No	No	No	No	No	No	No	No
118	118	No	No	No	No	No	No	No	No
119	119	No	No	No	No	No	No	No	No
120	120	No	No	No	No	No	No	No	No
121	121	No	No	No	No	No	No	No	No
122	122	No	No	No	No	No	No	No	No
123	123	No	No	No	No	No	No	No	No
124	124	No	No	No	No	No	No	No	No
125	125	No	No	No	No	No	No	No	No
126	126	No	No	No	No	No	No	No	No
127	127	No	No	No	No	No	No	No	No
128	128	No	No	No	No	No	No	No	No
129	129	No	No	No	No	No	No	No	No
130	130	No	No	No	No	No	No	No	No
131	131	No	No	No	No	No	No	No	No

Outfall Catchment System Vulnerability Factor (SVF) Inventory  
Granby, Massachusetts  
Revision Date: January 28, 2021

132	132	No	No	No	No	No	No	No	No
-----	-----	----	----	----	----	----	----	----	----

1. History of SSOs, including, but not limited to, those resulting from wet weather, high water table, or fat/oil/grease blockages
2. Common or twin-invert manholes serving storm and sanitary sewer alignments
3. Common trench construction serving both storm and sanitary sewer alignments
4. Crossings of storm and sanitary sewer alignments where the sanitary system is shallower than the storm drain system
5. Sanitary sewer alignments known or suspected to have been constructed with an underdrain system
6. Inadequate sanitary sewer level of service (LOS) resulting in regular surcharging, customer back-ups, or frequent customer complaints
7. Areas formerly served by combined sewer systems
8. Sanitary sewer infrastructure defects such as leaking service laterals, cracked, broken, or offset sanitary infrastructure, directly piped connections between storm drain and sanitary sewer infrastructure, or other vulnerability factors identified through Inflow/Infiltration Analyses, Sanitary Sewer Evaluation Surveys, or other infrastructure investigations